

G-TRAN Series 1-Channel Display Unit Model ISG1 Instruction Manual



This manual is for the display units of the following serial numbers:

Serial No. 09501 and higher.

Read this manual before operation and keep it at hand for immediate reference.

Model	Serial numbers
Multi Ionization Gauge ST200-A	00001~
Multi Ionization Gauge SH200-A	00001~
Multi Ionization Gauge ST2-1	00901~
Multi Ionization Gauge SH2-1	06001~
Cold-Cathode Ion Gauge SC1	02300G~
Pirani Vacuum Gauge SW100-A	00001~
Pirani Vacuum Gauge SW1-1	00001~
Pirani Vacuum Gauge SP1	00001~
Ceramic Capacitance Manometer CCMT-D series	00001~

Components Division, ULVAC, Inc. http://www.ulvac.co.jp/en

Prior to Operation

Upon receipt of this detector, make sure that it is the correct model you ordered and that it is not damaged in transit.

WARNING	Read this instruction manual before installing, operating, inspecting, or maintaining the product and fully understand the safety precautions, specifications and operating procedures regarding the product.
MARN I NG	The copyright of this instruction manual is held by ULVAC, Inc. You are prohibited from copying any portion of this instruction manual without the consent of ULVAC Inc. You are also prohibited from disclosing or transferring this instruction manual to third parties without the express written consent of ULVAC Inc.
A CAUTION	The contents described in this instruction manual are subject to change without prior notice because of changes in specifications or because of product improvements.

Safety Notations

	Safety symbols are used throughout this instruction manual to call the
WARNING	operator's attention to safety. The terminology used in safety symbols is
	classified below.

	Indicate status of urgency of danger when failure to comply with DANGER results in serious personal injury or death
	The work ignoring this warning will lead to serious damage to human life or
	ractory racinty (including this equipment) at a high probability.
	Indicate status of danger when failure to comply with WARNING results in
	serious worker's injury or death.
	The work ignoring this warning will cause possibility leading to serious
	damage to human life or factory facility (including this equipment).
	Indicate status of danger when failure to comply with WARNING results in
	minor injury or moderate damage.
	The work ignoring this warning will cause possibility leading to minor
	damage to worker or breakage to equipment or necessary to adjust.
✓ Note	Direct hazard is not existed, describe the necessity to know from the viewpoint of worker's safety or correct and safe operation of equipment

Safety Precautions

For safe operation of this unit, read this manual and the following safety precautions.

A	Servicing
MARNING	For repair and servicing, contact your local ULVAC representative or
	Components Division, ULVAC, Inc., Japan.
	<u>Turn OFF power.</u>
MARNING	If the unit fails, immediately turn off the power.
	Use of a failed unit may cause a fire or electric shock.
	Turn off power.
	If the unit gets unusually hot or gives off smoke or unusual smell,
	immediately turn off the power. Otherwise, fire can result.
	Power supply
	Before turning on the power to this instrument, make sure that the
	operating voltage and supply power are in agreement. If incorrect power is connected to this instrument and devices connected to this instrument may
	fail or fire may result. The over voltage comes under Category 1
	Protective grounding
	Ground the sensor with class D (class 3) grounding. If the sensor is not
	correctly connected it will not only show the wrong pressure there is a
	risk of damage to the sensor and the equipment connected to the sensor
	and a risk of fire
	Power supply
	The unit may only be connected to supply and measurement units that
	conform to the requirements of a grounded protective extra-low voltage
	(SELV-E according to EN 61010). The connection to the gauge has to be
	fused.
A	Power cable
ATACAUTION	The power cable is not packed in the same case. Use a cable having a
	sufficient current capacity.
	Installing an external switch in the power line
	This unit has no power switch. Install an external switch, breaker and
	over-current protector.
	<u>Check connection</u>
	See to it that the connection cables do not come into contact with other
	Conducting parts.
CAUTION	Do not disassemble this unit
	Do not modify
	Do not modify this unit. If modified, its actions are not warranted. Also
	fire or electric snock can result.
	Be careful of operating environment.
	Do not use the unit in a place where it may be splashed with water. If it
	I swing cables
	Before turning on power install the display cable sensor unit sensor
	and others
	Keen out foreign objects
	If any foreign objects, such as metals or combustibles. are admitted into
	the unit through an opening, remove them. Also keep foreign objects away
	from the terminals on the rear panel of the unit. Otherwise, the unit may
	be damaged.
	Discarding
/1 \CAUTION	If this unit is discarded, follow the regulations of your local government.
	Incidentally, expenses for disposing of this unit are on the user's account.

	Operating conditions
	Use this unit within the scope of the environment set forth in the
	specification.
	<u>Maintenance</u>
	The electric circuit in this instrument uses aluminum electrolytic
	capacitors. Generally speaking, the life of the aluminum electrolytic
	capacitor becomes short as the ambient temperature rises. To prevent
	components from damage, it is recommended to conduct maintenance at
	ULVAC about once every 3 years.
A	Cautions in shipping the unit
$ / \cap CALITION$	If the unit is to be shipped back to ULVAC, pack it in the original
	condition. If it is shipped bare, it may be damaged.

Revision History

DATE	No.	Reason
Apr. 4, 2008	03	S/N:00001 \sim first version
Aug. 25, 2009	04	• Added CCMT-1000D/100D/10D/1D
		Section 2.1, added output impedance to specifications.
		Chapter 22, added EC DECLARATION OF CONFORMITY.
		Chapter 18, added Interlock function.
July 27, 2011	05	Changed A5 version to B6 version.
		Added multi-ionization gauge SH2
Mar. 1, 2012	06	S/N:01482~
		Added SH2 (SPU combination mode), SH2 (SAU triple combination mode)
June 1, 2012	07	Corrected an error.
June 12, 2012	08	Corrected an error.
Sept. 10, 2013	09	BMR2 and BPR2 were discontinued.
		• Chapter 10, added that in SC1 when it is lower than the measuring lower limit,
		"HuF" is displayed and the output voltage is 10V.
Jun. 7, 2014	10	S/N:04050~
		Added connection check in combination mode of SH2.
		Notice: SH2 before S/N:01000 does not output a set point.
		• Chapter 5, displayed the sensor which is set in the program mode
		• Chapter 6, added [nc] which means that the sensor is not set and the setting is
		factory default to the sensor unit selection.
July 7, 2014	11	Corrected an error.
Oct. 9, 2015	12	Added multi-ionization gauge ST2.
Nov. 21, 2017	13	Added the explanation of CALCULATION function to the pressure conversion
		expression of each sensor.
Apr.20, 2018	14	Added the Measurement units function.
Jul.3, 2018	15	Added the Measurement display range function.
Oct.10, 2019	16	Added Pirani Vacuum gauge Measuring Unit SWU
		Corrected an error.
Dec.25, 2020	17	Section 2.2, Delete the instruction manual CD from the standard accessories.
		Section 2.1, Revised CE standard.
		Section 26, Revised EC Declaration of Conformity.
Mag 15, 2021	10	Section 27, Revised certificate of Decontamination.
Mar.15, 2021	18	Added multi tomization gauge SH200,S1200
0 -+ 10, 2022	10	A da d Direction SW/100
Oct. 19, 2022	19	Added Pirani gauge SW100 Corrected CE reference number of the standard
		Correction of EU Declaration of Conformity
		LIKCA Declaration of Conformity added
		Corrected an error
July 27, 2011 Mar. 1, 2012 June 1, 2012 June 12, 2012 Sept. 10, 2013 Jun. 7, 2014 July 7, 2014 Oct. 9, 2015 Nov. 21, 2017 Apr.20, 2018 Jul.3, 2018 Oct.10, 2019 Dec.25, 2020 Mar.15, 2021 Oct.19, 2022	05 06 07 08 09 10 11 12 13 14 15 16 17 18 19	 Chapter 18, added Interlock function. Changed A5 version to B6 version. Added multi-ionization gauge SH2 S/N:01482~ Added SH2 (SPU combination mode), SH2 (SAU triple combination mode) Corrected an error. BMR2 and BPR2 were discontinued. Chapter 10, added that in SC1 when it is lower than the measuring lower limit, "HuF' is displayed and the output voltage is 10V. S/N:04050~ Added connection check in combination mode of SH2. Notice: SH2 before S/N:01000 does not output a set point. Chapter 5, displayed the sensor which is set in the program mode Chapter 6, added 『nc』 which means that the sensor is not set and the setting is factory default to the sensor unit selection. Corrected an error. Added the weaplanation of CALCULATION function to the pressure conversion expression of each sensor. Added the Measurement units function. Added the Measurement display range function. Added the Measurement display range function. Added the Measurement of Conformity. Section 2.2, Delete the instruction manual CD from the standard accessories. Section 2.7, Revised CE standard. Section 2.7, Revised CE bandard. Section 2.7, Revised CE bandard. Section 2.7, Revised CE standard. Section 2.7, Revised CE bandard. Section 2.7, Revised CE tandard. Section 2.1, Re

Contents

			Page
Prior to	o Opera	ition	ii
Safety	Notatio Dragon	ons	
Salety .	Precau on Hist	nons	111 V
Conten	ts		vi
1.	GET	TING STARTED	1
1.1.		Overview of G-TRAN Series	1
1.2.		Terminology	1
1.3.		Features of This Unit	2
2.	SPE	CIFICATIONS AND COMPONENTS	3
2.1.		Specifications	3
2.2.		Standard Accessories	5
2.3.		Options	5
2.4.		Dimensional Drawings DIN Panel Size	6
2.5.		Installation DIN Panel	7
2.6.		Dimensional Drawings JIS panel size	8
3.	NAN	AES OF COMPONENTS AND DESCRIPTION OF FUNCTIONS	9
3.1.		Front Panel Lights	9
3.2.		Front Panel Switch Program Mode	
3.3.		Front Panel Switch Measurement Mode	11
3.4.		Rear Panel	
3.5.		Sensor Connector (D-sub 15pin connector socket, M2.6mm screw)	
3.6.		I/O Connector (D-sub 15pin connector pin, M2.6mm screw)	14
3.7.		Power Supply Connector (Phoenix model MSTB 2.5/3-GF-5.08)	
4.	INS	TALLATION	16
4.1.		Preparations	16
4.2.		Installation	
4	4.2.1.	Installing the display unit	
4	4.2.2.	Circuit in the power supply	
4	1.2.3.	Installation	
5.	PRO	GRAM MODE OPERATION	
5.1.		Description of Program mode	
6.	SEL	ECTION OF SENSOR UNIT	19
6.1.		Selection of Sensor Unit	
6.2.		Key operation in measurement	
6.3.	~==	Reset the Unit to the Factory Default Settings	
1.	SET	POINT	21
7.1.		What is Setpoint?	

	7.2.	Setpoint Setting Range	21	
	7.3.	How to Set Setpoint	21	
	7.3.1.	How to Set Setpoint from Front Panel	•••••	22
	7.3.2.	How to set setpoint from RS-485		23
8.	CON	NECTION WITH EXTERNAL DEVICES	24	
:	8.1.	Output Signal	24	
:	8.2.	Input Signal	25	
	8.2.1.	RS-485 communication		25
9.	PIRA	NI GAUGE SW100-A/SW1-1	26	
	9.1.	Sensor Unit Setting: "SP2"		
1	9.2.	Front Panel		
	9.2.1.	Pressure display state	••••••	26
	9.2.2.	Description of front panel keys	•••••	26
	9.3.	Setting Operation		
	9.3.1.	RS-485 communication operation setting "L1", "L2"		27
	9.3.2.	Front panel, external I/O operation setting: "AJ"	•••••	27
	9.3.3.	Method of setting	•••••	27
	9.4.	Connection with Sensor Unit		
	9.5.	Connection to External Device		
9	9.6.	Various Signals		
	9.6.1.	Output voltage		28
	9.6.2.	Filament disconnection signal		29
	9.6.3.	Zero point adjustment and atmospheric pressure adjustment		29
	9.6.4.	Setpoint		29
	9.6.5.	RS-485 communication		29
	9.7.	Zero Point Adjustment and Atmospheric Pressure Adjustment	29	
	9.7.1.	Adjusting method		29
10.	COLI	D CATHODE GAUGE SC1	30	
	10.1.	Setting the Sensor Unit	30	
	10.2.	Front Panel	30	
	10.2.1.	Pressure display		30
	10.2.2.	Front panel key description		30
	10.3.	Settings Operation	30	
	10.3.1.	RS-485 communication operation setting "L1", "L2"		30
	10.3.2.	Front panel, external I/O operation setting: "Hi"		30
	10.3.3.	Operation setting method		31
	10.4.	Connection to the Sensor Unit: "SENSOR" Connector	32	
	10.5.	Connection with External Devices: "I/O" Connector	32	
	10.6.	Signals	32	
	10.6.1.	Output voltage		32

	10.6.2.	HV ON signal: Pin 5	33
	10.6.3.	Discharge check signal: Pin 4	33
	10.6.4.	Setpoint: Pins 3, 7, 11	33
11	10.6.5.	RS485 communication: Pins 10, 12	33
11.	PIRA	NI GAUGE BPR2/SPI	
1	1.1.	Sensor Unit Setting: "SP1"	
1	1.2.	Front Panel	
	11.2.1.	Pressure display	34
	11.2.2.	Description of front panel keys	34
1	1.3.	Setting Operation	
	11.3.1.	RS-485 communication operation setting "L1", "L2"	34
	11.3.2.	Operation setting method	35
1	1.4.	Connecting to the Sensor Unit	
1	1.5.	Connection with External Devices	
1	1.6.	External Input/Output Signal	
	11.6.1.	Output voltage	36
	11.6.2.	Burnout signal	37
	11.6.3.	Setpoint	37
	11.6.4.	RS-485 communication	37
12.	HOT	CATHODE GAUGE BMR2	
1	2.1.	Sensor Unit Setting: "Sn1"	
1	2.2.	Front Panel	
	12.2.1.	Pressure display	38
	12.2.2.	Description of front panel keys	38
1	2.3.	Setting Operation	
	12.3.1.	Setting overview	38
	12.3.2.	RS-485 communication operation setting "L1", "L2"	39
	12.3.3.	Front panel, external I/O operation setting	39
	12.3.3	.1. Filament operation setting "F1"	39
	12.3.3	.2. Degas operation setting "dE"	39
	12.3.3	3. Filament changeover setting "FL"	
	1233	4 Operation setting method	40
1	24	Connection with the Sensor Unit 41	
1	2. 4 . 2.5	Connection with External Devices 41	
1	2.5.	Various Signals 42	
1	12.0.	Various Signals	12
	12.0.1.	Element on signal	42
	12.0.2.		42
	12.6.3.	Degas on signal	
	12.6.4.	Filament 1/2 changeover signal	42
	12.6.5.	Pressure protection signal	43

YK06-0044-EI-003-19

	12.6.6.	Emission valid signal	43
	12.6.7.	Setpoint	43
	12.6.8.	RS485 communication	43
13.	MUL	TI IONIZATION GAUGE SH200-A/ST200-A/SH2-1/ST2-144	
13	.1.	Sensor Unit Setting: "Sh2"	
13	.2.	Front Panel	
	13.2.1.	Pressure display	44
	13.2.2.	Description of front panel keys	44
13	.3.	Setting Operation	
	13.3.1.	Setting overview	45
	13.3.2.	RS-485 communication operation setting "L1", "L2"	45
	13.3.3.	Front panel, external I/O operation setting	45
	13.3.3	.1. Filament operation setting "Fi"	45
	13.3.3	.2. Degas operation setting "dE"	45
	13.3.3	.3. Filament changeover setting "FL"	45
	13.3.3	.4. Operation setting method	46
13	.4.	Connection with the Sensor Unit	
13	.5.	Connection with External Devices	
13	.6.	Various Signals	
	13.6.1.	Output voltage	48
	13.6.2.	Filament on signal	48
	13.6.3.	Degas on signal	48
	13.6.4.	Filament1/2 changeover signal	49
	13.6.5.	Pressure protection signal	49
	13.6.6.	Emission valid signal	49
	13.6.7.	Setpoint	49
	13.6.8.	RS-485 communication	49
14.	MUL	TI-IONIZATION GAUGE SH200-A/ST200-A/SH2-1/ST2-1 (SPU combination	
	mode)	
14	.1.	Sensor Unit Setting: "SPU"	
14	.2.	Front Panel	
	14.2.1.	Pressure display	50
	14.2.2.	Description of front panel keys	51
14	.3.	Setting Operation	
	14.3.1.	Setting Overview	51
	14.3.2.	RS-485 communication operation setting "L1", "L2"	51
	14.3.3.	Front panel, external I/O operation setting	51
	14.3.3	.1. Filament operation setting "Fi"	51
	14.3.3	.2. Degas operation setting "dE"	51
	14.3.3	.3. Filament changeover setting "FL"	51

	14.3.3	.4. Operation setting method	52
14	.4.	Connection with the Sensor Unit	
14	.5.	Connection with External Devices	
14	.6.	Various Signals	
	14.6.1.	Output voltage	54
	14.6.2.	Filament off signal	54
	14.6.3.	Degas on signal	55
	14.6.4.	Filament1/2 changeover signal	55
	14.6.5.	Sensor error signal	55
	14.6.6.	Emission valid signal	55
	14.6.7.	Setpoint	55
	14.6.8.	RS-485 communication	55
15.	Multi	Ionization Gauge SH200-A/ST200-A/SH2-1/ST2-1 (SAU combination mode)	
1.5			
15	.1.	Sensor Unit Setting: "SAU"	
15	.2.	Front Panel	50
	15.2.1.	Pressure display	56
15	15.2.2.	Setting Operation 57	
15	.5.	Setting Operation	57
	15.3.1.	Setting overview	
	15.3.2.	RS-485 communication operation setting "L1", "L2"	57
	15.3.3.	Front panel, external I/O operation setting	57
	15.3.3	2 D c c c c c c c c c c c c c c c c c c	57
	15.3.3	2. Elle () estimation setting "dE"	57
	15.3.3	4. Que di unita di la	
15	15.3.3.	4. Operation setting method	58
15	.4.	Connection with External Davison	
15		Various Signals 60	
15	1561		60
	15.0.1.	ilement off signal	00
	15.6.2	Deges on signal	01
	15.6.4	Eilament 1/2 changeover signal	01
	15.6.5	Sensor error signal	61
	15.6.5	Emission valid signal	61
	15.67	Setnoint	61
	15.6.7.	RS-485 communication	61
16.	MUL'	TI IONIZATION GAUGE SH200-A/ST200-A/SH2-1/ST2-1 (SWU combination)	01
16	.1.	Sensor Unit Setting: "SAU"	

16.2.	Front Panel	
16.2.1.	Pressure display	62
16.2.2.	Description of front panel keys	63
16.3.	Setting Operation	
16.3.1.	Setting overview	63
16.3.2.	RS-485 communication operation setting "L1", "L2"	63
16.3.3.	Front panel, external I/O operation setting	63
16.3.3	3.1. Filament operation setting "Fi"	63
16.3.3	3.2. Degas operation setting "dE"	63
16.3.3	3.3. Filament changeover setting "FL"	63
16.3.3	3.4. Operation setting method	64
16.4.	Connection with the Sensor Unit	
16.5.	Connection with External Devices	
16.6.	Various Signals	
16.6.1.	Output voltage	66
16.6.2.	Filament off signal	67
16.6.3.	Degas on signal	67
16.6.4.	Filament 1/2 changeover signal	67
16.6.5.	Sensor error signal	67
16.6.6.	Emission valid signal	67
16.6.7.	Setpoint	67
16.6.8.	RS-485 communication	67
17. CCM	I SERIES CERAMIC CAPASITANCE MANOMETER	68
17.1.	Sensor Unit Setting	
17.2.	Front Panel Display	
17.2.1.	Pressure display	
17.2.2.	Front panel operation	
17.3.	Operation setting	
17.3.1.	RS-485 communication operation setting "L1", "L2"	
17.3.2.	Front panel and external I/O operation setting "AJ"	69
17.3.3.	Setting method	69
17.4.	Connection to Sensor Unit	
17.5.	Connection to external device	
17.6.	Signals	
17.6.1.	Output voltage	
17.6.2.	Setpoint	71
17.6.3.	RS-485 communication	71
17.7.	ZERO Point Adjustment	71
17.7.1.	Operation front panel	71

17	.7.2.	Operation external I/O		71
17	.7.3.	RS-485 communication		71
18.	CAL	CULATING FUNCTION	72	
18.1.		Display Pressure Value in CAL Function	72	
18.2.		Output voltage in CAL function mode	72	
18.3.		Setting CAL value	72	
18.4.		Specific Sensitivity Value of Gas in Hot Cathode Ionization Gauge	73	
18.5.		CAL Value of Measurement Unit		
19.	INTE	RLOCK FUNCTION	74	
19.1.	MEA	Interlock Setting		
20.	MLA	Magurament Units Setting	75	
20.1.	MEA	SUREMENT DISPLAY RANGE SETTING		
21.1.		Measurement display Range rA Setting		
22.	RS-48	85	78	
22.1.		Communication Specifications		
22	.1.1.	Standard specifications		78
22	.1.2.	Communication setting		78
22.2.		Setting		
22	.2.1.	RS-485 communication setting "L2"		78
22	.2.2.	Baud rate setting		78
22	.2.3.	Address setting		78
22	.2.4.	Setting the checksum collating function		79
22	.2.5.	Setting the terminator		79
22	.2.6.	Setting method		80
22.3.		Standard Data Format		
22	.3.1.	Command list		82
22	.3.2.	When received normally		82
22	.3.3.	When receiving is faulty		82
22.4.		Command		
22	.4.1.	Reading the measurement value/status		83
22	.4.2.	Writing status		83
22	.4.3.	Reading a status		83
22	.4.4.	Reading the software version		83
22	.4.5.	Reading setpoint1 value		83
22	.4.6.	Reading the setpoint2 value		83
22	.4.7.	Reading the setpoint3 value		84
22	.4.8.	Writing the setpoint1 set value		84
22	.4.9.	Writing the setpoint2 set value		84
22	.4.10.	Writing the setpoint3 set value		84

YK06-0044-EI-003-19

22	.4.11.	1. SW1 ZERO point adjustment command		
22	.4.12.	2. SW1 atmospheric pressure adjustment command		84
22	22.4.13. SW1 zero point, atmospheric pressure adjustment correction reset command			84
22	22.4.14. CCM zero point adjustment command			85
22	.4.15.	Zero point, atmospheric pressure adjustment correction reset command		85
22.5.		Checksum	85	
22	.5.1.	Example: when reading the measurement value of address 11 and status		85
22.6.		Status Setting List	86	
22	.6.1.	When writing		86
22	2.6.2.	When reading		87
22.7.		ASCII Code Table	88	
23.	TROU	UBLESHOOTING	89	
24.	WARRANTY			
25.	China RoHS Declaration			
26.	EC DECLARATION OF CONFORMITY			
27.	UKC	UKCA DECLARATION OF CONFORMITY		
28.	Certif	ficate of Decontamination	95	

1. GETTING STARTED

1.1. Overview of G-TRAN Series

Units of the G-TRAN series vacuum gauges are varied in type and include the following types. "Sensor Unit" indicates all models and types of box units and sensor units throughout this manual. as of Oct. 2022

Unit Major classification	Unit Minor classification	Specification	Туре	Model
	Box unit	Analog/communication	Pirani	BPR2*
	Dox unit		Ionization	BMR2*
		Analog	Pirani	SP1
		Analog	CCG	SC1
		Analog/communication	Pirani (atmospheric pressure)	SW100/SW1
				SH200
Maggingenant		A	Ionization,	SH2*
wieasurement		sor unit	multi ionization	ST200
um	Sensor unit			ST2*
		SH200/ST200/	Dinoni	CDU
		SH2*/ST2* dedicated	FITAIII	SPU
		SH200/ST200/	Dironi	SWI10 D
		SH2*/ST2* dedicated	r II alli	3 W 010-K
		SH200/ST200/	Dressure concor	SAU
		SH2*/ST2* dedicated	Pressure sensor	SAU
		Analog	Diaphragm	CCMT-D
	1011		Pirani/ionization/	
	ICH Digital	DC24V	CCG/diaphragm/	ISG1
Display unit	Digital		multi ionization	
	4CH	DC24V	Pirani/ionization/	IM1R1*
	Digital	AC100V	CCG/multi ionization	IM2R1*

*: End of sale

1.2. Terminology

The following terms have the same meanings throughout this manual.

¥	¥ ¥	
Program	PROGRAM	PROG
Filament	FILAMENT	FIL
High voltage	HIGH VOLTAGE	HV
Degas	DEGAS	DEG
Zero	ZERO	ZERO
Setpoint	SETPOINT	ST
Error signal	ERROR	Err
Protection (pressure)	PROTECT	PRT
Emission valid	Emission Valid, Em.Valid	E.V.
Communication mode	Remote mode	RS-MODE
CAL function	CALCULATING FUNCTION	CAL

Pirani vacuum gauge	Pirani gauge	PG
Hot cathode ionization vacuum gauge	Hot cathode gauge	IG
Cold cathode ionization vacuum gauge	Cold cathode gauge	CCG
Diaphragm vacuum gauge	Ceramic capacitance manometer	CCM

1.3. Features of This Unit

• This display unit is for exclusive use with G-TRAN series:

	Sensor unit SP1
	Sensor unit SW100-A
Pirani gauge	Sensor unit SW1-1
	Box unit BPR2
Cold cathode gauge	SC1
Hot cathode gauge	Box unit BMR2
	SH200-A
	SH2-1
	SH200-A: SWU Combination mode
	(SH200-A+SWU10-R)
	SH2-1: SWU Combination mode
	SH200-A: SPU Combination mode
	(SH200-A+SPU)
	SH2-1: SPU Combination mode
	SH200-A: SAU Combination mode
	(SH200-A+SWU10-R/SPU+SAU)
	SH2-1: SAU Combination mode
Multi ionization gauge	ST200-A
	ST2-1
	ST200-A: SWU Combination mode
	(ST200-A+SWU10-R)
	ST2-1
	ST200-A: SPU Combination mode
	(ST200-A+ SWU10-R/SPU)
	ST2-1
	ST200-A: SAU Combination mode
	(ST200-A+SPU+SAU)
	ST2-1
Ceramic capacitance manometer	CCM series

• By connecting the sensor unit, measured pressure can be easily displayed, setpoint and other operations can be performed easily, and the operating state can be checked at a glance.

- Measurement can be made by remote operation via a display unit.
- Two independent pressure setpoints are available
- Compact size compatible with DIN standards (48mm × 96mm)
- Serial communication RS-485 is included.
- CE marking
- Environment-friendly display compatible with RoHS directives.

2. SPECIFICATIONS AND COMPONENTS2.1. Specifications

Name		1-channel digital display unit ISG1		
Number	of sensor units	1 pc.		
connected	d	-		
Sensor ur	nit	G-TRAN	Pirani sensor unit SP1	4.0×10^{-1} to $3.0 \times 10^{+3}$ Pa
		series	Pirani box unit BPR2	4.0×10 to 3.0×10 Fa
			Pirani sensor unit	5.0×10 ⁻² to 1.0×10 ⁺⁵ Pa
			SW100-A*2	5.0~10 10 1.0~10 1 a
			Pirani sensor unit SW1-1	5.0×10^{-2} to $1.2 \times 10^{+5}$ Pa
			Cold cathode ionization gauge SC1	1.0×10^{-5} to $1.0 \times 10^{+0}$ Pa
			Hot cathode ionization gauge BMR2	5.0×10 ⁻⁸ to 9.9×10 ⁺⁰ Pa
			Multi ionization gauge SH200-A/SH2-1	5.0×10 ⁻⁸ to 1.0×10 ⁺¹ Pa
			Multi ionization gauge SH200-A/SH2-1 (SWU combination mode)	5.0×10 ⁻⁸ to 1.0×10 ⁺⁵ Pa
			Multi ionization gauge SH200-A/SH2-1 (SPU combination mode)	5.0×10 ⁻⁸ to 1.0×10 ⁺⁴ Pa
			Multi ionization gauge SH200-A/SH2-1 (SAU combination mode)	5.0×10 ⁻⁸ to 1.0×10 ⁺⁵ Pa
			Multi ionization gauge ST200-A/ST2-1	1.0×10 ⁻⁵ to 1.0×10 ⁺¹ Pa
			Multi ionization gauge ST200-A/ST2-1 (SWU combination mode)	1.0×10 ⁻⁵ to 1.0×10 ⁺⁵ Pa
			Multi ionization gauge ST200-A/ST2-1 (SPU combination mode)	1.0×10 ⁻⁵ to 1.0×10 ⁺⁴ Pa
			Multi ionization gauge ST200-A/ST2-1 (SAU combination mode)	1.0×10 ⁻⁵ to 1.0×10 ⁺⁵ Pa
		Ceramic capacitance	CCMT-1000A/1000D CCMH-1000A	$0.0 \times 10^{+1}$ to $1.3 \times 10^{+5}$ Pa *1
		manometer	CCMT-100A/100D CCMH-100A	$0.0 \times 10^{+0}$ to $1.3 \times 10^{+4}$ Pa *1
			CCMT-10A/10D CCMH-10A	0.0×10^{-1} to $1.3 \times 10^{+3}$ Pa *1
			CCMH-1A CCMT-1D	0.0×10^{-2} to $1.3 \times 10^{+2}$ Pa *1
Analog ir	nput	Reading the	analog signal (voltage) from	the sensor
	Update time	70msec		
	Internal	5 times movi	ng average	
	processing			
D	Resolution	0.2mV		
Display		Digital displa	ay of mantissa part 2 digits, e	exponential part 1 digit
	Unit	Pa, Torr, mb	ar	
	Pressure range	Pressure rang	ge of each sensor unit	
	Update time	200msec		
	Accuracy	$\begin{array}{c} \pm 2\% \pm 1 \text{ dig} \\ \ast \text{ CCM serie} \end{array}$	it against the pressure value s: 1/10 or less of the full scal	from the measurement unit $e \pm 4 \text{ digits}$

Analog output		DC0V to 10V pseudo-log. output, log, linear output		
		* The output differs depending on the unit to be connected.		
	Update time	70msec		
	Resolution	1mV		
	Output error	±10mV		
	Impedance	100Ω		
	Accuracy	± 10 mV against the voltage converted value of pressure di	splay	
Cont	trol input signal	Actuated by open collector input, negative logic.	1 2	
	1 6	Filament, etc. ON/OFF signal, zero point adjustment sign	al, etc.	
Cont	trol output signal	Open collector output, negative logic.		
		[Rating: DC30V _{MAX} , 50mA _{MAX} , 70mW]		
		Signal of error, filament and other on signal and others		
		Setpoints1, 2, 3		
LED	display	SET-1, SET-2, SET-3		
		ERROR, DEG, ZERO		
Com	munication	RS-485		
	Baud rate	9600/19200/38400 bps		
	Number of nodes	32 (including host)		
	Distance	1200m		
		*Please check a specification of remote host and an environ	nmental noise	
		if you use the cable of 30m or more.		
	Memory function	Set value by communication is backed up by EEPROM.		
CAL	function	Arbitrary value $[1.0 \times 10^{-3} \text{ to } 1.0 \times 10^{+3}]$ is multiplied by the	e	
		measurement value and displayed.		
Line	voltage	DC24V±1V Ripple and noise below 1%		
Curr	ent consumption	2W (display unit alone)		
		*Power consumption by other interfaced units is to be added.		
~		Maximum 30W (when BRM2 is used)		
Corre	esponding standard	CE standard, UKCA standard		
Over	-voltage category	Category I: Connected to a circuit that holds down transie	ent over-	
		voltage at a sufficiently low level.		
T/O				
I/O c	connector			
I/O c	Sensor unit side	D-sub 15pin connector socket, M2.6mm screw		
I/O c	Sensor unit side Control host side	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw		
I/O o	Sensor unit side Control host side Power supply	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw Phoenix model MSTB 2.5/3-GF-5.08		
I/O c	Connector Sensor unit side Control host side Power supply nected cable length	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw Phoenix model MSTB 2.5/3-GF-5.08 Length of cable from this unit to the sensor unit, calculate 24AWG.	ed with	
I/O c	Sensor unit side Control host side Power supply nected cable length	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw Phoenix model MSTB 2.5/3-GF-5.08 Length of cable from this unit to the sensor unit, calculate 24AWG. Pirani sensor unit SP1	ed with	
I/O c	Connector Sensor unit side Control host side Power supply nected cable length	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw Phoenix model MSTB 2.5/3-GF-5.08 Length of cable from this unit to the sensor unit, calculate 24AWG. Pirani sensor unit SP1 Pirani box unit BPR2	ed with up to 50m up to 100m	
I/O c	Connector Sensor unit side Control host side Power supply nected cable length	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw Phoenix model MSTB 2.5/3-GF-5.08 Length of cable from this unit to the sensor unit, calculate 24AWG. Pirani sensor unit SP1 Pirani box unit BPR2 Pirani gauge SW100-A/SW1-1	ed with up to 50m up to 100m up to 100m	
I/O c	Connector Sensor unit side Control host side Power supply nected cable length	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw Phoenix model MSTB 2.5/3-GF-5.08 Length of cable from this unit to the sensor unit, calculate 24AWG. Pirani sensor unit SP1 Pirani box unit BPR2 Pirani gauge SW100-A/SW1-1 Cold cathode ion gauge SC1	ed with up to 50m up to 100m up to 100m up to 100m	
I/O c	Sensor unit side Control host side Power supply nected cable length	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw Phoenix model MSTB 2.5/3-GF-5.08 Length of cable from this unit to the sensor unit, calculate 24AWG. Pirani sensor unit SP1 Pirani box unit BPR2 Pirani gauge SW100-A/SW1-1 Cold cathode ion gauge SC1 Hot cathode ion gauge BMR2	ed with up to 50m up to 100m up to 100m up to 100m up to 10m	
I/O c	Sensor unit side Control host side Power supply nected cable length	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw Phoenix model MSTB 2.5/3-GF-5.08 Length of cable from this unit to the sensor unit, calculate 24AWG. Pirani sensor unit SP1 Pirani box unit BPR2 Pirani gauge SW100-A/SW1-1 Cold cathode ion gauge SC1 Hot cathode ion gauge BMR2 Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1	ed with up to 50m up to 100m up to 100m up to 100m up to 10m up to 40m	
I/O c	connector Sensor unit side Control host side Power supply nected cable length	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw Phoenix model MSTB 2.5/3-GF-5.08 Length of cable from this unit to the sensor unit, calculate 24AWG. Pirani sensor unit SP1 Pirani box unit BPR2 Pirani gauge SW100-A/SW1-1 Cold cathode ion gauge SC1 Hot cathode ion gauge BMR2 Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1	ed with up to 50m up to 100m up to 100m up to 100m up to 10m up to 40m up to 40m	
I/O c	connector Sensor unit side Control host side Power supply nected cable length	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw Phoenix model MSTB 2.5/3-GF-5.08 Length of cable from this unit to the sensor unit, calculate 24AWG. Pirani sensor unit SP1 Pirani box unit BPR2 Pirani gauge SW100-A/SW1-1 Cold cathode ion gauge SC1 Hot cathode ion gauge BMR2 Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SWU/SPU combination)	ed with up to 50m up to 100m up to 100m up to 100m up to 10m up to 40m up to 40m	
I/O c	Sensor unit side Control host side Power supply nected cable length	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw Phoenix model MSTB 2.5/3-GF-5.08 Length of cable from this unit to the sensor unit, calculate 24AWG. Pirani sensor unit SP1 Pirani box unit BPR2 Pirani gauge SW100-A/SW1-1 Cold cathode ion gauge SC1 Hot cathode ion gauge BMR2 Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SWU/SPU combination) Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1	ed with up to 50m up to 100m up to 100m up to 100m up to 10m up to 40m up to 40m up to 40m	
I/O c	Sensor unit side Control host side Power supply nected cable length	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw Phoenix model MSTB 2.5/3-GF-5.08 Length of cable from this unit to the sensor unit, calculate 24AWG. Pirani sensor unit SP1 Pirani box unit BPR2 Pirani gauge SW100-A/SW1-1 Cold cathode ion gauge SC1 Hot cathode ion gauge BMR2 Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SWU/SPU combination) Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SAU combination)	ed with up to 50m up to 100m up to 100m up to 100m up to 10m up to 40m up to 40m up to 40m	
I/O c	connector Sensor unit side Control host side Power supply nected cable length	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw Phoenix model MSTB 2.5/3-GF-5.08 Length of cable from this unit to the sensor unit, calculate 24AWG. Pirani sensor unit SP1 Pirani box unit BPR2 Pirani gauge SW100-A/SW1-1 Cold cathode ion gauge SC1 Hot cathode ion gauge BMR2 Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SWU/SPU combination) Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SAU combination) Ceramic capacitance manometer CCMT series	ed with up to 50m up to 100m up to 100m up to 100m up to 10m up to 40m up to 40m up to 40m up to 40m	
I/O c	connector Sensor unit side Control host side Power supply nected cable length	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw Phoenix model MSTB 2.5/3-GF-5.08 Length of cable from this unit to the sensor unit, calculate 24AWG. Pirani sensor unit SP1 Pirani box unit BPR2 Pirani gauge SW100-A/SW1-1 Cold cathode ion gauge SC1 Hot cathode ion gauge BMR2 Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SWU/SPU combination) Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SAU combination) Ceramic capacitance manometer CCMT series Ceramic capacitance manometer CCMH series	ed with up to 50m up to 100m up to 100m up to 100m up to 10m up to 40m up to 40m up to 40m up to 40m up to 100m up to 100m	
I/O c	connector Sensor unit side Control host side Power supply nected cable length	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw Phoenix model MSTB 2.5/3-GF-5.08 Length of cable from this unit to the sensor unit, calculate 24AWG. Pirani sensor unit SP1 Pirani box unit BPR2 Pirani gauge SW100-A/SW1-1 Cold cathode ion gauge SC1 Hot cathode ion gauge BMR2 Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SWU/SPU combination) Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SAU combination) Ceramic capacitance manometer CCMT series Ceramic capacitance manometer CCMH series 10°C to 40°C	ed with up to 50m up to 100m up to 100m up to 100m up to 10m up to 40m up to 40m up to 40m up to 40m up to 100m up to 100m	
I/O c Cont Oper range	connector Sensor unit side Control host side Power supply nected cable length rating temperature	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw Phoenix model MSTB 2.5/3-GF-5.08 Length of cable from this unit to the sensor unit, calculate 24AWG. Pirani sensor unit SP1 Pirani box unit BPR2 Pirani gauge SW100-A/SW1-1 Cold cathode ion gauge SC1 Hot cathode ion gauge BMR2 Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SWU/SPU combination) Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SAU combination) Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SAU combination) Ceramic capacitance manometer CCMT series Ceramic capacitance manometer CCMH series 10°C to 40°C	ed with up to 50m up to 100m up to 100m up to 100m up to 10m up to 40m up to 40m up to 40m up to 40m up to 100m up to 100m	
I/O c Conr Oper range Oper	connector Sensor unit side Control host side Power supply nected cable length rating temperature e rating humidity range	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw Phoenix model MSTB 2.5/3-GF-5.08 Length of cable from this unit to the sensor unit, calculate 24AWG. Pirani sensor unit SP1 Pirani box unit BPR2 Pirani gauge SW100-A/SW1-1 Cold cathode ion gauge SC1 Hot cathode ion gauge BMR2 Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SWU/SPU combination) Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SAU combination) Ceramic capacitance manometer CCMT series Ceramic capacitance manometer CCMH series 10°C to 40°C	ed with up to 50m up to 100m up to 100m up to 100m up to 10m up to 40m up to 40m up to 40m up to 40m up to 100m up to 100m	
Conr Conr Oper rang Oper Stora	connector Sensor unit side Control host side Power supply nected cable length reating temperature e rating humidity range	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw Phoenix model MSTB 2.5/3-GF-5.08 Length of cable from this unit to the sensor unit, calculate 24AWG. Pirani sensor unit SP1 Pirani box unit BPR2 Pirani gauge SW100-A/SW1-1 Cold cathode ion gauge SC1 Hot cathode ion gauge BMR2 Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SWU/SPU combination) Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SAU combination) Ceramic capacitance manometer CCMT series Ceramic capacitance manometer CCMH series 10°C to 40°C 15% to 80% (not condensing) -20°C to 65°C (non-operating, not condensing)	ed with up to 50m up to 100m up to 100m up to 100m up to 40m up to 40m up to 40m up to 40m up to 100m up to 100m	
I/O c Conr Oper rang Oper Stora Weid	connector Sensor unit side Control host side Power supply nected cable length rating temperature e rating humidity range age	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw Phoenix model MSTB 2.5/3-GF-5.08 Length of cable from this unit to the sensor unit, calculate 24AWG. Pirani sensor unit SP1 Pirani box unit BPR2 Pirani gauge SW100-A/SW1-1 Cold cathode ion gauge SC1 Hot cathode ion gauge BMR2 Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SWU/SPU combination) Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SAU combination) Ceramic capacitance manometer CCMT series Ceramic capacitance manometer CCMH series 10°C to 40°C 15% to 80% (not condensing) -20°C to 65°C (non-operating, not condensing) 250g	ed with up to 50m up to 100m up to 100m up to 100m up to 10m up to 40m up to 40m up to 40m up to 40m up to 100m up to 100m	
I/O c Cont Oper range Oper Stora Weig Outs	connector Sensor unit side Control host side Power supply nected cable length rating temperature e rating humidity range age ght ide dimensions	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw Phoenix model MSTB 2.5/3-GF-5.08 Length of cable from this unit to the sensor unit, calculate 24AWG. Pirani sensor unit SP1 Pirani box unit BPR2 Pirani gauge SW100-A/SW1-1 Cold cathode ion gauge SC1 Hot cathode ion gauge BMR2 Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SWU/SPU combination) Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SAU combination) Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SAU combination) Ceramic capacitance manometer CCMT series Ceramic capacitance manometer CCMT series 10°C to 40°C 15% to 80% (not condensing) -20°C to 65°C (non-operating, not condensing) 250g DIN 48mm × 96 mm basic unit 70mm deep	ed with up to 50m up to 100m up to 100m up to 100m up to 10m up to 40m up to 40m up to 40m up to 40m up to 100m up to 15m	
I/O c Conr Oper range Oper Stora Weig Outs	connector Sensor unit side Control host side Power supply nected cable length rating temperature e rating humidity range age ght ide dimensions	D-sub 15pin connector socket, M2.6mm screw D-sub 15pin connector pin, M2.6mm screw Phoenix model MSTB 2.5/3-GF-5.08 Length of cable from this unit to the sensor unit, calculate 24AWG. Pirani sensor unit SP1 Pirani box unit BPR2 Pirani gauge SW100-A/SW1-1 Cold cathode ion gauge SC1 Hot cathode ion gauge BMR2 Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SWU/SPU combination) Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1 (SAU combination) Ceramic capacitance manometer CCMT series Ceramic capacitance manometer CCMT series 10°C to 40°C 15% to 80% (not condensing) -20°C to 65°C (non-operating, not condensing) 250g DIN 48mm × 96 mm, basic unit 70mm deep IIS rack size 50mm × 100mm is also available as option	ed with up to 50m up to 100m up to 100m up to 100m up to 10m up to 40m up to 40m up to 40m up to 40m up to 100m up to 15m	

- *1: In the pressure display of the CCM series, the lowest digit is 1.0, 2.0 ... 9.0, and the decimal point is not displayed.
- *2: When SW100-A is connected, if the OUTPUT setting of SW100-A is PSG or APG, ISG1 is not supported. The pressure value is displayed, but it is not displayed correctly.

2.2. Standard Accessories

Power connector	MSTB 2.5/3-STF-5.08 made by PHOENIX	1 pc.
DIN panel fixing tools	fitting	1 set
Quick manual		1 pc.

2.3. Options

AC Adapter	OUTPUT: DC24V, INPUT: AC90 to 264V
JIS rack size type	
Display unit cable	2, 5, 10, 15, 20, 25, 30, 35, 40m long
	(between ISG1 and sensor unit)
Sensor unit	See section 1.3
Sensor	Refer to the instruction manual of each sensor unit.
D-sub 15pin connector female	M2.6mm screw, for sensor connector
D-sub 15pin connector male	M2.6mm screw, for I/O connector
JCSS calibration certificate	Only combination with sensor unit
Calibration certificate	Only combination with sensor unit
Inspection certificate	
Traceability certificate	

2.4. Dimensional Drawings DIN Panel Size













2.5. Installation DIN Panel



YK06-0044-EI-003-19

2.6. Dimensional Drawings JIS panel size



Ζ6 001

3. NAMES OF COMPONENTS AND DESCRIPTION OF FUNCTIONS

3.1. Front Panel Lights



		Lit when setpoint is actuated.
Û	SE1-1	Blinks when a setpoint value is being set.
O SET 2	SET_2	Lit when setpoint2 is actuated.
4	511-2	Blinks when a setpoint value is being set.
③ SET-3	SET 3	Lit when setpoint3 is actuated.
	SE1-3	Blinks when a setpoint value is being set.
	EDDUD	Lit or blinks when the sensor head filament has disconnect or in
4	EKKOK	other errors.
4	DEG	Lit when DEGAS is on.
		(only when SH200-A/ST200-A/SH2-1/ST2-1/BMR2 is selected.)
		Lit when the zero point is being adjusted.
		(only when the ceramic capacitance manometer is selected.)
6	ZERO	Lit when turns off the filament.
		(only when SWU combination mode/SPU combination mode/SAU
		combination mode of SH200-A/ST200-A/SH2-1/ST2-1 is selected.)

3.2. Front Panel Switch Program Mode



3.3. Front Panel Switch Measurement Mode



3.4. Rear Panel



SENSOR



Fig. 3.5 Sensor Connector Pin Assignment
(D-sub 15pin connector socket, M2.6mm screw)

Terminal No. *	Description	Signal direction	Connected to
1	+24V power output	OUT	
2	Sensor error input	IN	
3	Not used		
1	FIL/HV input,	IN	
4	Unit connection check signal	111	
5	FIL/HV ON, adjustment output	OUT	
6	FIL 1/2 output	OUT	
7	Not used		
8	Pressure signal input +	IN	Sensor unit
9	Power supply GND	OUT	
10	Not used		
11	Not used		
12	Not used		
13	DEGAS ON output	OUT	
14	Not used		
15	Pressure signal input -	IN	1
Case	FG		
* Do not wire the	e 'Not used" part, which is used for the inte	ernal circuit.	1





Fig. 3.6 I/O Connector Pin Assignment (D-sub 15pin connector pin, M2.6mm screw)

Terminal No. *	Description	Signal direction	Connected to
1	Not used	-	
2	Error signal output	OUT	_
3	Setpoint1 actuating signal	OUT	
4	FIL/HV output signal	OUT	Remote host
5	FIL/HV on, adjustment input signal	IN	
6	FIL1/2 input signal	IN	_
7	Setpoint3 actuating signal	OUT	
8	Recorder output +	OUT	Remote host/recorder
9	Signal GND	OUT	Remote host/recorder
10	RS485-	IN/OUT	Remote host/PC
11	Setpoint2 actuating signal	OUT	Remote host
12	RS485+	IN/OUT	Remote host/PC
13	DEGAS ON input signal	IN	Remote host
14	Not used	-	
15	Signal GND	OUT	Remote host/recorder
<i>a</i>	FG		





4. INSTALLATION

A CAUTION	Operating environment Use this instrument within the scope of the environment set forth in the specifications.
AUTION	Keep out foreign objects If any foreign objects, such as metals or combustibles, are admitted into the unit through an opening, remove them. Also keep foreign objects away from the terminals on the rear panel of the unit. Otherwise, the unit may be damaged.

4.1. Preparations

- (1) Unpack the case and check quantities. (Refer to section 2.2 for the accessories.)
- (2) Check components to see if any of them is damaged in transit.

4.2. Installation

4.2.1. Installing the display unit

Ensure ventilation When two or more sets are attached, please leave space of 20mm or more each in the direction of a side. When you put into a power supply rack etc., please take heat dissipation into consideration.

Refer to section 2.4, 2.5 and 2.6 for the installation.

4.2.2. Circuit in the power supply

· ·	Down downly
MARN I NG	Power suppy Before turning on the power to this instrument, make sure that the operating voltage and supply power are in agreement. If incorrect power is connected, this instrument and devices connected to this instrument may fail or fire may result. The over-voltage comes under Category 1.
	Laying cables
	When laying transmission lines for communication, see to it that they are
	not in the proximity of, or parallel to, power lines, high voltage lines, high
	frequency lines, etc. Otherwise, malfunction can result.
	Protective grounding
	Ground the sensor with class D (class 3) grounding. If the sensor is not
	correctly connected, it will not only show the wrong pressure, there is a risk
	of damage to the sensor and the equipment connected to the sensor and a risk
	<u>Power source</u>
	The unit may only be connected to supply and measurement units that
	confirm to the requirement to the requirements of a grounded protective extra-
	low voltage (SELV-E according to EN 61010). The connection to the unit has
	to be fused.
	Laying cables
	Before turning on power, install the display cable, sensor unit, sensor, and
	others.

- Fix the cable in such a way that undue force is not exerted to cable connections, such as power cable, display cable, external I/O cable, sensor head cable and others.
- Securely tighten the screws for fixing connectors.
- Do not mistake the pin No. in supplying power to this instrument. (See section 3)
- For the connection of the sensor unit and the sensor, refer to the manual for the sensor unit.



Fig. 4.1 Equivalent Circuit in the Power Supply

4.2.3. Installation



5. PROGRAM MODE OPERATION

This section describes the operating procedure on the front panel.

1	The table below gives the operating procedure in the program mode.				
	Notation	Name	Function		
	PROG	Program keyEnters into the program mode. Also a key for shifting to each sett			
	\bigcirc	Upper arrow key	Key that changes a numeric value.		
	\downarrow	Right arrow key	Used when changing settings.		
		Enter key	Press at the end of an input.		

Enter key	Press at the end of an input.
Pressure display	
$ \neq \mathcal{Y}^{\vee}_{\mathbb{F}^{-2}} \text{ Setpoint 1 setting: SE'} $	Γ-1 LED blinks
Ug ⁻² Setpoint 2 setting: SE [*] □ PROG	Γ-2 LED blinks
$\mathcal{U}_{\mathcal{F}}^{\mathcal{F}^{\mathcal{F}}}$ Setpoint 3 setting: SE	Γ-3 LED blinks
$\begin{bmatrix} \mathbf{P} & \mathbf{C} \\ \mathbf{P} & \mathbf{C} \\ \mathbf{P} \\ \mathbf{P} \\ \mathbf{P} \\ \mathbf{P} \\ \mathbf{C} $	ng : see section on CALCULATION
RS485 setting : see sec	ction on RS 485
$ \int_{\nabla} \frac{1}{ \mathbf{PROG} } \text{Interlock setting} $	
	ling
	ange setting
Setting of each sensor : see \sqrt{PROG}	section on setting of each sensor
Selected sensor unit	

5.1. Description of Program mode The table below gives the operating procedure in the program mode.

6. SELECTION OF SENSOR UNIT

Before using this unit, select a sensor unit to connect to this unit.

6.1. Selection of Sensor Unit

The currently selected sensor unit blinks for 3sec after power is applied to this unit.

Press the $\stackrel{\frown}{\bigcirc}$ (up arrow) key while the sensor unit is blinking and, when the sensor unit is displayed, press the $\stackrel{\frown}{\smile}$ (enter) key. Each press on the up arrow key changes the sensor unit name as shown below.



Display of ISG1	Sensor unit to connect
пс	Non-selection
5 P 2	Pirani vacuum gauge SW100-A/SW1-1
5N ¹	Hot cathode gauge BMR2
ЕПЭ	Ceramic capacitance manometer CCMT-1000A/1000D/CCMH-1000A
ЕП 2	Ceramic capacitance manometer CCMT-100A/100D/CCMH-100A
ЕП '	Ceramic capacitance manometer CCMT-10A/10D/CCMH-10A
сп ¤	Ceramic capacitance manometer CCMT-1D/CCMH-1A
rn II	Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1
2 7 -	(SPU combination mode)
rn II	Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1
י חב	(SAU combination mode/SWU combination mode)
55 '	Cold cathode gauge SC1
5P 1	Pirani vacuum gauge BPR2, SP1
562	Multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1

		Sensor unit name					
Notation	Name	BPR2 /SP1	SW100-A /SW1-1	SC1	SH200-A/ST200-A /SH2-1/ST2-1 /BMR2	SWU/SPU /SAU Combination	CCM series
PROG	Program key						
ZERO	Zero point adjustment key	-	-	-	-	-	Zero point adjustment
DEG	Degas key	-	-	-	Degas	Degas	-
FIL	Filament key	-	Zero point adjustment, ATM pressure adjustment	HV ON	FIL ON	FIL OFF	-

6.2. Key operation in measurement

*This is the operation when the operation is selected from the front panel. For details, refer to the operation setting section of each unit in this manual.

6.3. Reset the Unit to the Factory Default Settings

The factory parameter setting is activated by keeping the "ZERO" key (\bigcirc (up arrow) key) depressed for at least 3sec after power on. So display is "nc". Select a sensor unit, check the setpoint value and calculation value.

Setti	ng	Set values		
Sensor uni	t	nc		
ST1		4.9E-2		
ST2		4.9E-2		
ST3		4.9E-2		
CAL		1.0E+0		
L1/L2		L1 (Operation of front panel and external I/O)		
In F (interlock OFF)		F (interlock OFF)		
rΛ	uP	1.4E+8		
IA	Lo	4.9E-b		
Filament on ,etc. F (Front panel operation mode)		F (Front panel operation mode)		

7. SETPOINT

↑ CAUTION	$\frac{\text{Display of 10^{-10}, 10^{-11}}}{10^{-10} \text{ is "A (A of capital letter)", 10^{-11} is "b (B of small letter)".}$
	Please note "b (B of small letter)" to make a mistake as '6' of the figure.
	Fast blinking of the setpoint value
I /I \ CAUTION	If the setpoint value blinks at high speed when you try to change the setpoint,
	it is set to RS-485 or interlock, so please check the setting.

This section describes the settings of setpoint.

Before reading this section, read the standard operating procedure described in the preceding sections.

7.1. What is Setpoint?

Setpoint is a function of outputting a signal to outside or lighting an LED when pressure has lowered to below a certain set level. The set pressure value is called "setpoint".

If a pressure being measured has lowered to below the setpoint,

Front panel : SET-1/SET-2/SET-3 LED light up.

External I/O : Each setpoint output becomes Lo.

RS-485 : 1 is set at each setpoint value of the status.

7.2. Setpoint Setting Range

The setpoint setting range of all sensors is the same. The setpoint range assumes the CALCULATION function.

Setpoint setting range: 4.9×10^{-11} to $1.4 \times 10^{+8}$ Pa

 10^{-10} is "A (A of capital letter)", 10^{-11} is "b (B of small letter)".Please note "b (B of small letter)" to make a mistake as '6' of the figure.

7.3. How to Set Setpoint

Setpoint can be set on the front panel or through RS-485. For the setting through RS-485, refer to section 22.

7.3.1. How to Set Setpoint from Front Panel



7.3.2. How to set setpoint from RS-485Refer to section 22 for how to set through RS-485.In the RS-485 mode, the setpoint value can be checked with the PROG key, but it cannot be changed.
8. CONNECTION WITH EXTERNAL DEVICES

The table below gives the pin assignment in the connection with external devices. *Connector for connection "I/O": D-sub 15pin socket (M2.6mm screw)

『I/O』 pin	Description	Remarks
2		Output signals such as error.
	Output signal	Lo when actuated, $DC30V_{MAX}$, $50mA_{MAX}$, $70mW$
2	Saturating signal	Output a signal when setpoint 1 actuates.
5	Setpoint actuating signal	Lo when actuated, DC30V _{MAX} , 50mA _{MAX} , 70mW
4	Output signal	Outputs FIL, E.V., and HV signals.
4	Output signal	Lo when actuated, DC30V _{MAX} , 50mA _{MAX} , 70mW
5	Input signal	Input signals such as FIL, HV, and adjust.
5	Input signal	Actuated when shorted with GND
6	Input signal	Input switching signal such as FIL 1/2.
0	Input signal	Actuated when shorted with GND
7	Setpoint3 actuating signal	Output a signal when setpoint 3 actuates.
/		Lo when actuated, DC30V _{MAX} , 50mA _{MAX} , 70mW
8	Pressure signal output+	Output pressure signal
0		DC0V to 10V
0	Signal GND	GND of pressure signal, filament disconnect signal,
2		setpoint, etc.
10	RS485-	Serial communication RS485- output
11	Setpoint2 actuating signal	Output a signal when setpoint 2 actuates.
11		Lo when actuated, DC30V _{MAX} , 50mA _{MAX} , 70mW
12	RS485+	Serial communication RS485+ output
12	Input signal	Input a DEGAS signal.
15		Actuated when shorted to GND
15	Signal CND	GND of pressure signal, filament disconnection signal,
13	Signal OND	setpoint, etc.
Case	FG	Frame ground

8.1. Output Signal

For the output of signals such as setpoint, the photocoupler operates and become a Lo signal. Photocoupler rating: DC30V_{MAX}, 50mA_{MAX}, 70mW



8.2. Input Signal

	Contact capacity
ANCAUTION	Use a capacity for externally installed contacts greater than the input power
	supply voltage and DC30V or higher.
	Contact leak current
	Be aware of contact leak current. If a current of 0.08mA or higher flows
	between the input signal pin to the GND terminal, that may be treated as
	signal input.

When input each signal, set each terminal to GND.



Fig.8-2 Input Signal

8.2.1. RS-485 communication Refer to section 22 for RS-485 communication.

9. PIRANI GAUGE SW100-A/SW1-1

	Connection with an analog output type SW100-A and a standard type
	SW1-1 is recommended.
ANCAUTION	Zero point and atmosphere adjustment will be impossible if it connects with
	a serial communication type SW100-R/SW1-2. Moreover, Filament error
	signal may not be outputted.
	Please use the OUTPUT setting of SW100-A with SW100-A/SW1-1.
	If the OUTPUT setting of SW100-A is used with PSG and APG, the
	pressure will be displayed, but it will not be converted to the correct
	pressure value.
	If the SW100-A OUTPUT settings are used with the SP1, follow the settings
	in Chapter 11.
	For OUTPUT setting, please refer to the SW100 instruction manual.

This section describes the operation of the sensor unit of the Pirani gauge SW100-A/SW1-1. Before reading this section, read the standard operating procedure in the preceding sections.

9.1. Sensor Unit Setting: "SP2"

Turn on the power to this unit and make sure that "SP2" lights for several seconds.

To display others, press the \bigcirc key several times within 3sec after turning on power to change over the display to "SP2" and make it definite with the \bigcirc key.

Refer to section 6 for more information about the sensor unit setting.

9.2. Front Panel

CAU

9.2.1. Pressure display state

Filament disconnection detection

If the main component of the measurement gas is hydrogen (H₂) or helium (He), this output signal may be output even if the filament is broken.

Condition	Pressure indicator	LED
In normal measurement	SW100-A: 5.0×10^{-2} Pa to $1.0 \times 10^{+5}$ Pa SW1-1 : 5.0×10^{-2} Pa to $1.2 \times 10^{+5}$ Pa	
Below measurement pressure range	0.0×10 ⁻² Pa	
Above measurement pressure range	F.F×10 ^{+F} Pa	
When filament has burnt out.		
(When filament disconnection signal	Err	ERROR LED lights
is input.)		
When filament has burnt out.		
(When filament disconnection signal	Err	
is not input.)		
When sensor unit is not connected.		ERROR LED lights

9.2.2. Description of front panel keys

Name (notation)	Function	Remarks
PROG	Enters into the program mode	Refer to section 5.
ZERO	Not used	
DEG	Not used	
FIL	Makes zero point and ATM adjustment	Cannot be operated when RS-485 and I / O are set

9.3. Setting Operation

The following settings are available for zero point and atmospheric pressure adjustment.

Setting	Overview
Front panel operation mode	Can be operated on the front panel only.
External I/O operation mode	Only external I/O can be operated.
RS-485 communication mode	Only RS-485 communication can be operated.

9.3.1. RS-485 communication operation setting "L1", "L2" Select whether zero point adjustment and atmospheric pressure adjustment are to be made through RS-485 communication or not.
Refer to section 22 for the detailed settings of RS-485

Refer to section 22 for the detailed settings of RS-485.			
Display	Detail		

Display	Detail	Remarks
"L1"	Operation of front panel and external I/O	RS-485: Pressure reading only
"L2"	Operation of only RS-485 communication	

9.3.2. Front panel, external I/O operation setting: "AJ"

Selects whether the zero point and atmospheric pressure adjustment are not be made on the front panel or with external I/O.

Display	Detail
"F"	Operation on the front panel only
"0"	Only I/O is operated.

9.3.3. Method of setting

Press the "PROG" key to change over the mode. Each press on the "PROG" key changes the mode as follows.

	Procesure display	
	PROG	
\rightarrow	$\mathcal{U} \overset{\bullet}{\mathcal{D}}^{\mathcal{Z}}$ ST1 setting: SET-1 LED blimks \longrightarrow Change the setting PROG	· · · · · · · · · · · · · · · · · · ·
	$\begin{array}{c} \downarrow & \downarrow \\ \downarrow & \downarrow \\ \blacksquare & \blacksquare \blacksquare \\ \blacksquare & \blacksquare \blacksquare \\ \blacksquare & \blacksquare \\ \blacksquare & \blacksquare \blacksquare \\ \blacksquare \\$	₽ ₽ ₽ −−−−
	$\psi q = 2$ ST3 setting: SET-3 LED blinks \longrightarrow Change the setting PROG	· · · · · · · · · · · · · · · · · · ·
	$ \begin{array}{c c} & \downarrow & L \\ & \square & \square & \square \\ & \square & \square & \square \\ & \square & \square &$	₽ ₽ ₽ −−−−
	\downarrow^{\vee} RS485 setting Display "11" or "12" \longrightarrow	طetermine —
	$\begin{array}{ c c c c c } \hline PROG \\ \hline & & & \\ \hline \\ \hline$	
	Select "1" or "2"	
	determine ↓	
	$ \begin{array}{c} & & \\ & & $	♪ ♪ ₽
	$\downarrow \square \square$ Measurement units setting \longrightarrow Change the setting	☆ ☆ ↓
	$= \square$ Measurement display range setting \longrightarrow Change the setting	▷ ▷ ▷ □
	PROG	
	$5 \stackrel{\lor}{P} \stackrel{?}{\sim} \text{Setting sensor : Displayed } 5 \stackrel{?}{P} \stackrel{?}{\longrightarrow} \longrightarrow$	determine
	$\begin{array}{c c} & & & \\ \hline H & & \\ \hline H & & \\ \hline H & & \\ \hline PROG & & \\ \hline \end{array} \\ \end{array} : display \\ \hline H & & \\ \hline H & & \\ \hline \end{array} $	طetermine —
	Select "F" or "o"	
	↓ ↓ determine	

9.4. Connection with Sensor Unit

- The table below gives the pin assignment in connecting with the sensor unit SW100-A or SW1-
- 1. In connecting with the sensor unit, it is recommended to connect all of the following pins.
 - * Connector for connection "SENSOR": D-sub 15pin connector pin, M2.6mm screw

"SENSOR"	Description	Remarks	Sensor unit
1	DC24V power	DC24V power to the sensor unit	1
2	Filament	Error signal is input when filament has	2
2	disconnection signal	disconnect.	2
5	ADJ adjustment	Makes zero point and ATM adjustment	5
8	Pressure signal input +	Pressure signal is input	8
9	Power GND	Power GND to the sensor unit	9
15	Pressure signal input -	Pressure signal is input	15
Case	FG	Frame ground	Case

* Connector for connection SW100-A/SW1-1: D-sub 15pin connector socket, M2.6mm screw

9.5. Connection to External Device

The table below gives the pin assignment in connecting with external devices.

* Connector for connection "I/O": D-sub 15pin connector socket, M2.6mm screw

"I/O"	Description	Remarks
2	Filament disconnection signal output	Lo when actuated, $DC30V_{MAX}$, $50mA_{MAX}$, $70mW$
3	Setpoint1 actuating signal	Lo when actuated, DC30V _{MAX} , 50mA _{MAX} , 70mW
5	Adjustment	Actuated when shorted to GND
7	Setpoint3 actuating signal	Lo when actuated, DC30V _{MAX} , 50mA _{MAX} , 70mW
8	Pressure signal output +	DC0V to 10V
9	Signal GND	GND of pressure signal, filament disconnection signal, setpoint, etc.
10	RS485-	Serial communication RS-485- output
11	Setpoint2 actuating signal	Lo when actuated, $DC30V_{MAX}$, $50mA_{MAX}$, $70mW$
12	RS485+	Serial communication RS-485+ output
15	Signal GND	GND of pressure signal, filament disconnection signal, setpoint, etc.
Case	FG	Frame ground

9.6. Various Signals

9.6.1. Output voltage

Output voltage is outputted with +[8pin] \rightarrow GND [15pin] of the I/O connector.

 $P=10^{(V-k)} \times C \leftrightarrow V=log(P/C)+k$

P: Pressure value

V: Measurement value output voltage (V)

C: Calculation value (Refer to below table or section 18)

k: Conversion factor (Refer to the table below)Measurement UnitkCPa3 $1.0 \times 10^{+0}$ Torr5.1249 7.5×10^3 mbar5 1.0×10^{-2}

Status	Measurement value output voltage
In normal measurement	Voltage corresponding to the measured pressure
Above the measurable higher limit	8.1V or higher
Below the measurable lower limit	1.7V or less
In case of filament disconnection	9V or higher



9.6.2. Filament disconnection signal

The filament disconnection signal is output when the sensor head filament has disconnect. If the filament disconnect, Lo is output in the open collector format.

Photocoupler rating: DC30V_{MAX}, 50mA_{MAX}, 70mW

In case of filament disconnection, "Err" is displayed on the front panel, but also it can be confirmed by reading the status from the I/O connector through RS-485 communication. Refer to the manual for sensor unit for the check method when the filament is disconnect.

9.6.3. Zero point adjustment and atmospheric pressure adjustment

Makes zero point adjustment and atmospheric pressure adjustment of SW100-A/SW1-1. + [5pin] of the I/O connector \rightarrow output with GND [15pin]

9.6.4. Setpoint

Refer to Section 7 for how to adjust and use the setpoint. Photocoupler rating: DC30V_{MAX}, 50mA_{MAX}, 70mW

9.6.5. RS-485 communication

Refer to section 22 for RS-485 communication.

9.7. Zero Point Adjustment and Atmospheric Pressure Adjustment

	Refer to the instructions manual of a sensor			
	Please read the instructions manual of sensor unit, when zero point			
adjusted and atmospheric pressure adjusted.				

9.7.1. Adjusting method

Zero point adjustment and atmospheric pressure adjustment can be made by the following method.

Adjusting Method	Operating procedure		
Front nonal	Adjustment	Hold down the "FIL" switch for 1sec or more.	
From panel	Adjustment reset	Hold down the "FIL" switch for 5sec or more.	
	Adjustment Adjustment reset	Turn on (short) "adjustment input" from I/O for 1sec or	
External L/O		more.	
		Turn on (short) "adjustment input" from I/O for 5sec or	
		more.	
RS-485	Input each command through serial communication		

10. COLD CATHODE GAUGE SC1

This section describes the operation of the cold cathode gauge SC1. Before reading this section, go through the standard operating procedure described in the preceding sections and the manual for the sensor unit.

10.1. Setting the Sensor Unit

Turn on the power to this unit and make sure that "Sc1" blinks for about 3sec.

In any other display appears, press the \bigcirc key within 3sec after turning on power and, after changing the display to "Sc1", make it definite with the \bigcirc key.

Refer to section 6 for more information about the sensor unit setting.

10.2. Front Panel

10.2.1. Pressure display

Condition	Pressure display	LED
In normal measurement	1.0×10^{-5} Pa to $1.0 \times 10^{+0}$ Pa	
Below measurement pressure range	$0.0 \times 10^{-5} \text{Pa}$	
Below measurable greatly lower limit ^{*1}	HuO	
Above measurement pressure range	HuO	
When HV is off when power is turned on	HuF	
Immediately after HV is turned on	HuO	
When discharge check signal is not yet connected ^{*2}	Pressure indication	Err blinks
When sensor unit is not connected		Err lights

*1: Below measurable greatly lower limit. Refer to the manual of SC1.

*2: The discharge check signal indicates that discharge current is flowing normally. The setpoint of this unit is not actuated unless this signal is input.

10.2.2.	Front	panel	key	description
---------	-------	-------	-----	-------------

Name (notation)	Function	Remarks
PROG	Enters into the program mode	Refer to section 5 and this section
ZERO	Not used	
DEG	Not used	
FIL	HV ON/OFF operation	Cannot be operated when RS-485 and external I/O are set

10.3. Settings Operation

The following settings are available for turning ON/OFF high voltage.

Setting	Overview
Front panel operation mode	Only the front panel can be operated
External I/O operation mode	Only external I/O can be operated
RS-485 communication mode	Only RS-485 communication can be operated

10.3.1. RS-485 communication operation setting "L1", "L2"

Select whether HV ON/OFF is to be operated by RS-485 communication or not.

Refer to section 22 for detailed setting of RS-485, commands and others.

Display	Detail	Remark
"L1"	Operation of front panel and external I/O	RS-485: Pressure reading only
"L2"	Only RS-485 communication operation	

10.3.2. Front panel, external I/O operation setting: "Hi"

Selects whether HV ON/OFF is to be operated on the front panel or with external I/O.

Display	Detail
"HiF"	Only operation on front panel
"Hio"	Only operation of I/O

10.3.3. Operation setting method

Press the <u>PROG</u> key to change over the mode. Each press on the <u>PROG</u> key changes the display as follows. If HV is on (local or remote), this unit cannot do HV settings operation.



10.4. Connection to the Sensor Unit: "SENSOR" Connector

The table below gives the pin assignment in the connection with the sensor unit. In the connection with the sensor unit, it is recommended to connect all of the following pins.

Connector for connection "SENSOR": D-sub 15pin connector male, M2.6mm screw
Connector for connection "SC1": D-sub 15pin connector female, M2.6mm screw

"SENSOR"	Description	Details	Sensor unit
1	DC24V power	DC24V power supply to the sensor unit	1
4	Discharge check signal ^{*1}	Signal showing that discharge: input	4
5	HV ON/OFF	HV ON/OFF signal: output	5
8	Pressure signal input+	Pressure signal: input.	8
9	Power GND	Power GND to the sensor unit	9
15	Pressure signal input-	Pressure signal: input.	15
Case	FG	Frame ground	Case

*1 The discharge check signal indicates that discharge current is flowing normally.

The setpoint of this instrument is not actuated unless this signal is input.

10.5. Connection with External Devices: "I/O" Connector

The table below gives the pin assignment in the connection with external devices.

* Connector for connection "I/O": D-sub 15pin connector female, M2.6mm screw

"I/O"	Description	Remarks
3	Setpoint1 actuating signal output	Lo when actuated, $DC30V_{MAX}$, $50mA_{MAX}$, $70mW$
4	Discharge check signal output	Lo when actuated, $DC30V_{MAX}$, $50mA_{MAX}$, $70mW$
5	HV ON/OFF signal input	Actuated when shorted to GND
7	Setpoint3 actuating signal output	Lo when actuated, $DC30V_{MAX}$, $50mA_{MAX}$, $70mW$
8	Pressure signal output+	DC0V to 10V
9	Signal GND	Signal GND
10	RS485-	Serial communication RS-485- output
11	Setpoint2 actuating signal output	Lo when actuated, $DC30V_{MAX}$, $50mA_{MAX}$, $70mW$
12	RS485+	Serial communication RS-485+ output
15	Signal GND	Signal GND
Case	FG	Frame ground

10.6. Signals

10.6.1. Output voltage

Output voltage is outputted with the I/O connector +[8pin] \rightarrow GND [15pin].

P=10×(V-E)×10^(E-8+C)

- P : Pressure value
- V : Measurement value output voltage (V)
- E : Measurement value output voltage V from which fractions are rounded off
- C : Exponent value of calculation value

(The value of C in A.B× 10° , refer to section 18)

The (V-E) calculated value may become 0.1 or lower due to errors in the sensor's output voltage and errors with the measuring instrument. If it falls below 0.1 in this manner, we recommend rounding up to 0.1 and calculating.

Status	Measurement value output voltage
In normal measurement	Voltage corresponding to the measured pressure
Above the measurable higher limit	8.1V or higher
Below the measurable lower limit ^{*1}	3V
When HV is off	10V
No discharge	10V
	11

*1: Refer to the manual of SC1.



10.6.2. HV ON signal: Pin 5

Before turning on HV, short pin 5 to GND with the external switch. When front panel operation or RS-485 communication is set, input of this signal will be invalid.

10.6.3. Discharge check signal: Pin 4

Start of discharge is output as a signal. If discharge occurs, the open collector will be Lo output. Photocoupler rating: DC30V_{MAX}, 50mA_{MAX}, 70mW

For more information about the discharge check signal and corrective actions against the discharge signal not being turned on, refer to the manual for the sensor unit.

10.6.4. Setpoint: Pins 3, 7, 11

Refer to section 7 for how to adjust and use the setpoint. Photocoupler rating: DC30V_{MAX}, 50mA_{MAX}, 70mW

10.6.5. RS485 communication: Pins 10, 12

Refer to section 22 for communication through RS-485.

11. PIRANI GAUGE BPR2/SP1

Power supply to the BPR2 CAULION If 24VDC is supplied to the BPR2, the display when the sensor unit is unconnected is shown. This section describes how to use the Pirani gauge BPR2 or SP1 sensor unit. Before reading this section, refer to the standard operating procedure in the foregoing sections. 11.1. Sensor Unit Setting: "SP1"

Turn on the power to this unit and make sure that "SP1" is lit for several seconds.

To display others, press the \bigcirc key several times within 3sec after turning on power to change

over the display to "SP1" and then make it definite with the \checkmark key. Refer to section 6 for more information about the settings of the sensor unit.

11.2. Front Panel

11.2.1. Pressure display

If the main component of the measurement gas is hydrogen (H₂) or helium (He), this Note output signal may be output even if the filament is broken.

Condition	Pressure indication	LED
In normal measurement	4.0×10^{-1} Pa to $3.0 \times 10^{+3}$ Pa	
Below measurement pressure range	$0.0 \times 10^{-1} \text{ Pa}$	
Above measurement pressure range	FFF	
When filament has burnt out	Err	Err I ED lights
(When filament burnout signal is input)	EII	EIT LED lights
When filament has burnt out	Frr	
(When filament burntout signal is not input)		
When the sensor unit is not connected		Err LED lights.

11.2.2. Description of front panel keys

Description (notation)	Function	Remarks
PROG	Enters into the program mode	Refer to section 5
ZERO	Not used	
DEG	Not used	
FIL	Not used	

11.3. Setting Operation

11.3.1. RS-485 communication operation setting "L1", "L2"

Select whether HV ON/OFF is to be operated by RS-485 communication or not.

Refer to Section 22 for detailed setting of RS-485, commands and others.

Display	Detail	Remarks
"L1"	Operation of front panel and external I/O	RS-485: Pressure reading only
"L2"	Only RS-485 communication operation	

11.3.2. Operation setting method

Press the <u>PROG</u> key to change over the mode. Each press on the <u>PROG</u> key changes the display as follows.



11.4. Connecting to the Sensor Unit

The table below gives the pin assignment in connecting to the sensor unit. In connecting to the sensor unit, it is recommended to connect all the following pins.

Connector for connection "SENSOR": D-sub 15pin connector male, M2.6mm screw
 Connector for connection "BPR2/SP1": D-sub 15pin connector female, M2.6mm screw

* Conn	* Connector for connection BPR2/SP1 : D-sub 15pin connector female, M2.6min screw		
"SENSOR"	Description	Remarks	Sensor unit
1	24VDC power supply	24VDC power supply to the sensor unit	1
2	Burnout signal	Error signal of filament burnout is input.	2
4	Measuring unit connection check signal	Measuring unit connection check signal is input.	4
8	Pressure signal input+	Pressure signal is input.	8
9	Power GND	Power GND to the sensor unit	9
15	Pressure signal input-	Pressure signal is input.	15
Case	FG	Frame ground	Case

11.5. Connection with External Devices

The table below gives the pin assignment in connecting to an external device.

* Conr	nector for connection "I/O": D-	sub 15pin connector female, M2.6mm screw
"I/O" pin	Description	Remarks
2	Burnout signal output	Lo when error, 30 VDC _{MAX} , 50 mA _{MAX} , 70 mW
3	Setpoint1 actuating signal	Lo when actuated 30VDC _{MAX} 50mA _{MAX} 70mW

3	Setpoint1 actuating signal	Lo when actuated, 30VDC _{MAX} , 50mA _{MAX} , 70mW
7	Setpoint3 actuating signal	Lo when actuated, 30VDC _{MAX} , 50mA _{MAX} , 70mW
8	Pressure signal output+	0V to 10VDC
9	Signal GND	GND of pressure signal, burnout signal, setpoint, etc.
10	RS485-	Serial communication RS-485- output
11	Setpoint2 actuating signal	Lo when actuated, $30VDC_{MAX}$, $50mA_{MAX}$, $70mW$
12	RS485+	Serial communication RS-485+ output
15	Signal GND	GND of pressure signal, burnout signal, setpoint, etc.
Case	FG	Frame ground

11.6. External Input/Output Signal

11.6.1. Output voltage

Output voltage output: I/O connector 4 [8pin] \rightarrow GND [15pin]

 $P=10 \times (V - E) \times 10^{(E-1)} + C$

P: Pressure value

V: Measured value output voltage (V)

- E: Measured value output voltage from which decimal point is omitted
- C: Exponent value of calculation value
 - (The value of C in $A.B \times 10^{C}$, refer to section 18)

The (V-E) calculated value may become 0.1 or lower due to errors in the sensor's output voltage and errors with the measuring instrument. If it falls below 0.1 in this manner, we recommend rounding up to 0.1 and calculating.

Condition	Measured output voltage
In normal measurement	Voltage corresponding to the measured pressure
When measurable higher limit is exceeded	5.1V
When lower than measurable lower limit	0V
When filament has burnt out	9V or higher



11.6.2. Burnout signal



12. HOT CATHODE GAUGE BMR2

CAUTION

Cable connecting the basic unit and BMR2

The cable (24AWG) connecting the basic unit and BMR2 is 10m long maximum. If a longer cable is necessary, connect the power source directly to the BMR2 or use a cable with a larger diameter.

This section describes the operation of the BMR2 ionization vacuum gauge.

Before reading this section, read the standard operating procedure in the foregoing sections.

12.1. Sensor Unit Setting: "Sn1"

Turn on the power to this unit and make sure that "Sn1" lights for several seconds.

To display others, press the \bigcirc key several times within 3sec after turning on power, change the display to "Sn1" and make it definite with the \bigcirc key.

For more information about the sensor unit setting, refer to Section 6.

12.2. Front Panel

12.2.1. Pressure display

Status	Pressure indicator	LED
In normal measurement	5.0×10^{-8} Pa to $9.9 \times 10^{+0}$ Pa	
Below measurement pressure range	0.0×10^{-8} Pa	
Above measurement pressure range and when pressure protection signal is input	Prt	
Above measurement pressure range and when pressure protection signal is not input	FiO	
When power is turned on	FiF	
Immediately after filament is turned on	FiO	
When degassing is on	Pressure indication	DEG is lit
When emission valid is off	Pressure indication	Err blinks
When sensor unit is not connected		Err lights

*1: When a CALCULATION function is used, it displays to 10⁻¹¹ at the minimum.

 10^{-10} is "A (A of capital letter)", 10^{-11} is "b (B of small letter)". Please note "b (B of small letter)" to make a mistake as '6' of the figure.

12.2.2. Description of front panel keys

Inscription	Function	Remarks
PROG	Enters into program mode	Refer to section 5
ZERO	Not used	
DEG	Degassing ON/OFF operation	Cannot be operated when RS-485 and external I/O are set
FIL	Filament ON/OFF operation	Cannot be operated when RS-485 and external I/O are set

12.3. Setting Operation

12.3.1. Setting overview

The following settings are available for turning on the filament or degassing and for changing over the filament 1/2.

Setting	Overview
RS-485 communication mode	Only RS-485 communication is available
Front panel operation mode	Only front panel operation is available
External I/O operation mode	Only external I/O operation is available

12.3.2. RS-485 communication operation setting "L1", "L2"

Selects if filament ON/OFF, degassing ON/OFF or filament1/2 changeover is to be operated through RS-485 communication. Refer to section 22 for more information about the detailed setting of RS-485.

Display	Details	Remarks
"L1"	Operation on the front panel and external I/O	RS-485: Pressure reading only
"L2"	Only operation through RS-485 communication	

12.3.3. Front panel, external I/O operation setting

12.3.3.1. Filament operation setting "F1"

Selects whether filament ON/OFF is to be operated on the front panel or with external I/O. This function will be invalidated if it is set at RS-485 communication.

Display	Detail
"F"	Operation on the front panel only
"0"	Operation of external I/O only

12.3.3.2. Degas operation setting "dE"

Selects whether degassing ON/OFF is to be operated on the front panel or with external I/O. This function will be invalidated if RS-485 communication is set.

Display	Detail
"F"	Operation on front panel only
"0"	Operation of external I/O only

12.3.3.3. Filament changeover setting "FL"

Selects whether selection of filament 1/2 is to be operated on the front panel or with external I/O. This function will be invalidated if it is set at RS-485 communication.

Also the filament set on the front panel will be invalidated when operation is changed over to external I/O.

Display	Detail
"0"	Operation of external I/O only
"1"	Setting of filament1
"2"	Setting of filament2

12.3.3.4. Operation setting method

Press the program key to change over the set mode. Each press on the program key changes over the display as follows. If filament is on (local or remote), this unit cannot do filament setting, degas setting, and filament1/2 setting.



12.4. Connection with the Sensor Unit

The table below gives the pin assignment in connecting to the sensor unit.

- In connecting to the sensor unit, it is recommended to connect all pins below.
- * Connector for connection "SENSOR": D-sub15 pin connector male, M2.6mm screw
- * Connector for connection "BMR2": D-sub15 pin connector female, M2.6mm screw

"SENSOR"	Description	Detail	Sensor unit
1	24VDC power supply	24VDC power supply to the sensor unit	1
2	Pressure protection	Protection signal in excess of the higher	2
2	signal	limit of measurement is input	2
4	Emission valid* ¹	Emission valid signal is input	4
5	Filament on	Filament on signal is output	5
6	Filament1/2 changeover	Outputs filament1/2 changeover signal	6
8	Pressure signal input+	Pressure signal is input	8
9	Power supply GND	Power supply GND to the sensor unit	9
13	Degas on	Degas on signal is output	13
15	Pressure signal input-	Pressure signal is input	15
Case	FG	Frame ground	Case

*1: The emission valid signal is a signal indicating that emission current is flowing normally. The setpoint of this instrument is not actuated unless this signal is input.

12.5. Connection with External Devices

The table below gives the pin assignment in the connection to external devices.

*	Con	nector	for	con	ne	ction	"I/O'	':	D-sub	15p	oin	connecto	r 1	female,	M2.6	ómm	screw
TIC	:		5		•									D	1		

"I/O"	Description	Remarks
2	Pressure protection signal	Lo when actuated, $30VDC_{MAX}$, $50mA_{MAX}$, $70mW$
3	Setpoint1 actuating signal	Lo when actuated, 30VDC _{MAX} , 50mA _{MAX} , 70mW
4	Emission valid	Lo when actuated, $30VDC_{MAX}$, $50mA_{MAX}$, $70mW$
5	Filament on	Actuated when shorted to GND
7	Setpoint3 actuating signal	Lo when actuated, $30VDC_{MAX}$, $50mA_{MAX}$, $70mW$
8	Pressure signal output+	0V to 10VDC
9	Signal GND	GND of pressure, burnout, setpoint, etc.
10	RS485-	Serial communication RS-485- output
11	Setpoint2 actuating signal	Lo when actuated, 30 VDC _{MAX} , 50 mA _{MAX} , 70 mW
12	RS485+	Serial communication RS-485+ output
13	Degas on	Actuated when shorted to GND
15	Signal GND	GND of pressure, burnout, setpoint, etc.
Case	FG	Frame ground

12.6. Various Signals

12.6.1. Output voltage

The output voltage is output with + [8pin] of the I/O connector \rightarrow GND [15pin] In case CAL function is enabled, the conversion formula is different from the above The equation for converting pressure:

 $P = 10 \times (V - E) \times 10^{\circ} (E - 8 + C)$

P: Pressure value

- V: Measurement value output voltage (V)
- E: Measured value output voltage from which decimal point is omitted

C: Exponent value of calculation value

(The value of C in A.B× 10° , refer to section 18)

The (V-E) calculated value may become 0.1 or lower due to errors in the sensor's output voltage and errors with the measuring instrument. If it falls below 0.1 in this manner, we recommend rounding up to 0.1 and calculating.

State	Measurement value output voltage
In normal measurement	Voltage corresponding to measured pressure
At above measurement higher limit	9.9V or higher
At below measurement lower limit	0.5V or less
When filament is off	9.9V or higher



12.6.2. Filament on signal

Signal that turns on the filament. To turn on the filament, connect it to GND with the external switch. In the case of front panel operation or RS-485 communication setting, input of this signal will be invalid.

12.6.3. Degas on signal

Signal that turns on degassing. To turn it on, connect it to GND with the external switch. In the case of front panel operation or RS-485 communication setting, input of this signal will be invalid.

12.6.4. Filament1/2 changeover signal

Signal that changes over filament1/2. To change it over to filament2, connect it to GND. In the case of front panel operation or RS-485 communication setting, input of this signal will be invalid.

12.6.5. Pressure protection signal

If the sensor unit exceeds the higher limit of measurement pressure, pressure protection will be actuated. If it is actuated, the open collector will be Lo output.

Photocoupler rating: 30V_{MAX}, 50mA_{MAX}, 70mW

For more information about pressure protection and actions in case of pressure protection signal being turned on, refer to the sensor unit manual.

12.6.6. Emission valid signal

When the emission current is flowing normally or not is output as a signal. If emission current is flowing normally, the open collector will be Lo output.

Photocoupler rating: 30V_{MAX}, 50mA_{MAX}, 70mW

For more information about the emission valid signal and corrective actions in case when the emission valid signal is turned off, refer to the sensor unit manual.

12.6.7. Setpoint

For how to adjust and use the setpoint, refer to section 7 Photocoupler rating: 30V_{MAX}, 50mA_{MAX}, 70mW

12.6.8. RS485 communication

For RS-485 communication, refer to section 22

13. MULTI IONIZATION GAUGE SH200-A/ST200-A/SH2-1/ST2-1

_	The support model of SH2-1 becomes manufacturing numbers after
	<u>06001</u>
	If manufacturing number of SH2-1 is before <u>06001</u> , this unit may not output
	setpoints.
•	The support model of ST2-1 becomes manufacturing numbers after
	<u>00901</u>
	If manufacturing number of ST2-1 is before 00901, this unit may not output
	setpoints.
	We recommended a connection with the analog output type
	When connecting to the serial communication type SH200-R/ST200-R
	/SH2-2/ST2-2, FIL ON, etc., cannot be performed with the sensor.
	Depending on the cable connection, there is a risk of damage to the SH200-
	R/ST200-R /SH2-2/ST2-2.
	Sensor and SH200-A/ST200-A/SH2-1/ST2-1 connection cable
^	The cable to connect the sensor and the SH200-A/ST200-A/SH2-1/ST2-1 has
	a maximum length of 40m for the 24AWG. To use the sensor with a cable
	longer than 40m, directly connect the SH200-A/ST200-A/SH2-1/ST2-1 to a
	power supply or increase the cable diameter.

This section describes the operation of the multi ionization gauge SH200-A/ST200-A/SH2-1/ST2-1.

Before reading this section, read the standard operating procedure in the foregoing sections.

13.1. Sensor Unit Setting: "Sh2"

Turn on the power to this unit and make sure that "Sh2" lights for several seconds.

To display others, press the \bigcirc key several times within 3sec after turning on power, change the display to "Sh2" and make it definite with the \bigcirc key.

For more information about the sensor unit setting, refer to Section 6

13.2. Front Panel

13.2.1. Pressure display

Status	Pressure indicator	LED
In normal measurement	5.0×10 ⁻⁸ Pa to 1.0×10 ⁺¹ Pa	
Below measurement pressure range	0.0×10 ⁻⁸ Pa	
Above measurement pressure range and when pressure protection signal is input	Prt	
Above measurement pressure range and when pressure protection signal is not input	FiO	
When power is turned on	FiF	
Immediately after filament is turned on	FiO	
When degassing is on	Pressure indication	DEG is lit
When emission valid is off	Pressure indication	Err blinks
When sensor unit is not connected		Err lights

*1: When a CALCULATION function is used, it displays to 10⁻¹¹ at the minimum.

 10^{-10} is "A (A of capital letter)", 10^{-11} is "b (B of small letter)". Please note "b (B of small letter)" to make a mistake as '6' of the figure.

13.2.2.	Description	of front	panel keys
---------	-------------	----------	------------

Inscription	Function	Remarks
PROG	Enters into program mode	Refer to Section 5 and this section
ZERO	Not used	
DEG	Degassing ON/OFF operation	Cannot be operated when RS-485 and external
		I/O are set
FIL	Filament ON/OFF operation	Cannot be operated when RS-485 and external
		I/O are set

13.3. Setting Operation

13.3.1. Setting overview

The following settings are available for turning on the filament or degassing and for changing over the filament 1/2.

Setting	Overview	
RS-485 communication mode	Only RS-485 communication is available	
Front panel operation mode	Only front panel operation is available	
External I/O operation mode	Only external I/O operation is available	

13.3.2. RS-485 communication operation setting "L1", "L2"

Selects if filament ON/OFF, degassing ON/OFF or filament1/2 changeover is to be operated through RS-485 communication. Refer to Section 22 for more information about the detailed setting of RS-485.

Display	Details	Remarks
"L1"	Operation on the front panel and external I/O	RS-485: Pressure reading only
"L2"	Only operation through RS-485 communication	

13.3.3. Front panel, external I/O operation setting

13.3.3.1. Filament operation setting "Fi"

Selects whether filament ON/OFF is to be operated on the front panel or with external I/O. This function will be invalidated if it is set at RS-485 communication.

Display	Detail	
"F"	Operation on the front panel only	
"0"	Operation of external I/O only	

13.3.3.2. Degas operation setting "dE"

Selects whether degassing ON/OFF is to be operated on the front panel or with external I/O. This function will be invalidated if RS-485 communication is set.

Display	Detail
"F"	Operation on front panel only
"0"	Operation of external I/O only

13.3.3.3. Filament changeover setting "FL"



Setting only filament1, if you used ST200-A/ST2-1 ST200-A/ST2-1 has only one filament. Setting only filament1.

Selects whether selection of filament1/2 is to be operated on the front panel or with external I/O. This function will be invalidated if it is set at RS-485 communication.

Also the filament set on the front panel will be invalidated when operation is changed over to external I/O.

Display	Detail	
"0"	Operation of external I/O only	
"1"	Setting of filament1	
"2"	Setting of filament2	

13.3.3.4. Operation setting method

Press the program key to change over the set mode. Each press on the program key changes over the display as follows. If filament is on (local or remote), this unit cannot do filament setting, degas Setting, and filament1/2 setting.



13.4. Connection with the Sensor Unit

The table below gives the pin assignment in connecting to the sensor unit.

- In connecting to the sensor unit, it is recommended to connect all pins below.
- * Connector for connection "SENSOR": D-sub 15pin connector pin, M2.6mm screw
- * Connector for connection "SH200-A/ST200-A/SH2-1/ST2-1": D-sub 15pin connector socket, M2.6mm screw

	W12.0html Selew		
"SENSOR"	Description	Detail	Sensor unit
1	DC24V power supply	DC24V power supply to the sensor unit	1
2	Pressure protect signal	Pressure protect signal is input	2
4	Emission valid ^{*1}	Emission valid is input	4
5	Filament off	Filament off signal is output	5
6	Filament1/2 changeover ^{*2}	Outputs filament1/2 changeover signal	6
-	FIL power monitor ^{*3}	Not used	7
8	Pressure signal input+	Pressure signal is input	8
9	Power supply GND	Power supply GND to the sensor unit	9
13	Degas on	Degas on signal is output	13
15	Pressure signal input-	Pressure signal is input	15
Case	FG	Frame ground	Case

*1: The emission valid signal is a signal indicating that the emission current is flowing normally. If this signal is not input, the set point of the instrument will not operate.

- *2: Not use in ST200-A/ST2-1.
- *3: This unit cannot use. The filament power monitor signal is a function that outputs a signal as on (low) when the power supplied to the filament of SH200-A/ST200-A/SH2-1/ST2-1 has exceed the specified value range.

13.5. Connection with External Devices

- The table below gives the pin assignment in the connection to external devices.
- * Connector for connection "I/O": D-sub 15pin connector socket, M2.6mm screw

"I/O"	Description	Remarks	
2	Pressure protection signal	Lo when actuated, DC30V _{MAX} , 50mA _{MAX} , 70mW	
3	Setpoint1 actuating signal	Lo when actuated, $DC30V_{MAX}$, $50mA_{MAX}$, $70mW$	
4	Emission valid	Lo when actuated, DC30V _{MAX} , 50mA _{MAX} , 70mW	
5	Filament on	Actuated when shorted to GND	
7	Setpoint3 actuating signal	Lo when actuated, DC30V _{MAX} , 50mA _{MAX} , 70mW	
6	Filament 1/2 changeover ^{*1}	Setting of Filament2 when shorted to GND	
8	Pressure signal output+	DC0V to 10V	
9	Signal GND	GND of pressure signal, burnout signal, setpoint, etc.	
10	RS485-	Serial communication RS485- output	
11	Setpoint2 actuating signal	Lo when actuated, DC30V _{MAX} , 50mA _{MAX} , 70mW	
12	RS485+	Serial communication RS485+ output	
13	Degas on	Actuated when shorted to GND	
15	Signal CND	GND of pressure signal, filament disconnection	
	Signal OND	signal, setpoint, etc.	
Case	FG	Frame ground	

*1: Setting only firament1, if you used ST200-A/ST2-1.

13.6. Various Signals

13.6.1. Output voltage

The output voltage is output with + [8pin] of the I/O connector \rightarrow GND [15pin] P = 10 ^ { (V - 7.25) / 0.75 + k } × C

$$\longleftrightarrow V = 7.25 + 0.75 \times \{ \log (P/C) - k \}$$

P: Pressure value

V: Measurement value output voltage (V)

C: Calculation value (Refer to below table or section 18)

k: Conversion factor (Refer to the table below)

Measurement Unit	k	С
Ра	2	$1.0 \times 10^{+0}$
Torr	-0.1249	7.5×10^{-3}
mbar	0	1.0×10^{-2}

State	Measurement value output voltage
In normal measurement	Voltage corresponding to measured pressure 0.27V to 6.5V
At above measurement higher limit	9.9V or higher
At below measurement lower limit	0.25V or less
When filament is off	9.9V or higher



13.6.2. Filament on signal

Signal that turns on the filament. When turning on the filament by operating with external I/O, connect to GND with an external switch. In the case of front panel operation or RS-485 communication setting, input of this signal will be invalid.

13.6.3. Degas on signal

Signal that turns on degassing. When turning on the degas by operating with external I/O, connect to GND with an external switch. In the case of front panel operation or RS-485 communication setting, input of this signal will be invalid.

13.6.4. Filament1/2 changeover signal

	Filament1/2 materials
	M-44/M-45/M-46: Both filament1 and filament2 are yttria-coated iridium
/1 \CAUIION	wire.
	M-34/M-35/M-36: Filament1 is a yttria-coated iridium wire.
	Filament2 is a tungsten wire.
	Setting only filament1, if you used ST200-A/ST2-1
	ST200-A /ST2-1 has only one filament. Setting only filament1.
<u> </u>	

Signal that changes over filament1/2. To change it over to filament2, connect it to GND. In the case of front panel operation or RS-485 communication setting, input of this signal will be invalid.

13.6.5. Pressure protection signal

If the sensor unit exceeds the higher limit of measurement pressure, pressure protection will be actuated. If it is actuated, the open collector will be Lo output.

Photocoupler rating: DC30V_{MAX}, 50mA_{MAX}, 70mW

For more information about pressure protection and actions in case of pressure protection signal being turned on, refer to the sensor unit manual.

13.6.6. Emission valid signal

When the emission current is flowing normally or not is output as a signal. If emission current is flowing normally, the open collector will be Lo output.

Photocoupler rating: DC30V_{MAX}, 50mA_{MAX}, 70mW

If an emission error occurs during SH200-A/ST200-A/SH2-1/ST2-1 measurement, it can be released by turning off the SH200-A/ST200-A/SH2-1/ST2-1 filament.

For more information about the emission valid signal and corrective actions in case when the emission valid signal is turned off, refer to the sensor unit manual.

13.6.7. Setpoint

For how to adjust and use the setpoint, refer to section 7 Photocoupler rating: DC30V_{MAX}, 50mA_{MAX}, 70mW

13.6.8. RS-485 communication

For RS-485 communication, refer to section 22

14. MULTI-IONIZATION GAUGE SH200-A/ST200-A/SH2-1/ST2-1 (SPU combination mode)

	The support model of SH2-1 becomes manufacturing numbers after
	<u>06001</u>
	If manufacturing number of SH2-1 is before <u>06001</u> , this unit may not
	output setpoints.
	The support model of ST2-1 becomes manufacturing numbers after
	<u>00901</u>
	If manufacturing number of ST2-1 is before 00901, this unit may not output
	setpoints.
We recommended a connection with the standard type	
CAUTION	When connecting to the serial communication type SH200-R/ST200-
	R/SH2-2/ST2-2, FIL ON, etc., cannot be performed with the sensor.
	Depending on the cable connection, there is a risk of damage to the
	SH200-R/ST200-R/SH2-2/ST2-2.
	Sensor and SH200-A/ST200-A/SH2-1/ST2-1 connection cable
	The cable to connect the sensor and the SH200-A/ST200-A/SH2-1/ST2-1 has
/1 \CAUTION	a maximum length of 40m for the 24AWG. To use the sensor with a cable
	longer than 40m, directly connect the SH200-A/ST200-A/SH2-1/ST2-1 to a
	power supply or increase the cable diameter.

This section describes the operation of the multi ionization vacuum gauge SH200-A/ST200-A/SH2-1/ST2-1 (SPU combination mode). Before reading this section, read the standard operating procedure in the foregoing sections.

14.1. Sensor Unit Setting: "SPU"

Turn on the power to this unit and make sure that "SPU" lights for several seconds.

To display others, press the \bigcirc key several times within 3sec after turning on power, change the display to "SPU" and make it definite with the \bigcirc key.

For more information about the sensor unit setting, refer to section 6

- 14.2. Front Panel
- 14.2.1. Pressure display

Status	Pressure indicator	LED
In normal measurement	5.0×10^{-8} Pa to $1.0 \times 10^{+4}$ Pa	
Below measurement pressure range	0.0×10^{-8} Pa	
Above measurement pressure range	F.F×10 ^{+F} Pa	
When error of SH200-A/ST200-A/SH2-1/ST2-1	Pressure indication more than	Err I ED lights
(When error signal is input)	1.0×10^{-1} Pa	EII EED lights
When error of Pirani gauge	Err	Err I ED lights
(When error signal is input)	(Setpoints off)	EIT LED lights
When error of Pirani gauge	Err	
(When error signal is not input)	(Setpoints off)	
SH200-A/ST200-A/SH2-1/ST2-1	Display is pressure	Err LED
Emission valid off ^{*1}	(Setpoints off)	blinks
When SH200-A/ST200-A/SH2-1/ST2-1	Dressure indication	DEC is lit
degassing is on	Pressure indication	DEG IS III
SH200-A/ST200-A/SH2-1/ST2-1 FIL OFF	Pressure indication more than	
511200 7451200 745112 1/512-1 TIL OFT	1.0×10^{-1} Pa	

*1: However, the error of SH200-A/ST200-A/SH2-1/ST2-1 is cleared by turning FIL off (Forced FIL OFF).

*: When a CALCULATION function is used, it displays to 10^{-11} at the minimum.

 10^{-10} is "A (A of capital letter)", 10^{-11} is "b (B of small letter)". Please note "b (B of small letter)" to make a mistake as '6' of the figure.

Inscription	Function	Remarks
PROG	Enters into program mode	Refer to Section 5 and this section
ZERO	Not used	
	Degagaing ON/OFF operation	Cannot be operated when RS-485 and external
DEG	Degassing ON/OFF operation	I/O are set
т т	Filament forced off operation	Cannot be operated when RS-485 and external
1 IL		I/O are set

14.2.2. Description of front panel keys

14.3. Setting Operation

14.3.1. Setting Overview

The following settings are available for turning on the filament or degassing and for changing over the filament1/2.

Setting	Overview
RS-485 communication mode	Only RS-485 communication is available.
Front panel operation mode	Only front panel operation is available.
External I/O operation mode	Only external I/O operation is available

14.3.2. RS-485 communication operation setting "L1", "L2"

Selects if filament off, degassing ON/OFF or filament1/2 changeover is to be operated through RS-485 communication. Refer to section 22 for more information about the detailed setting of RS-485.

Display	Details	Remarks	
"L1"	Operation on the front panel and external I/O	RS-485: Pressure reading only	
"L2"	Only operation through RS-485 communication		

14.3.3. Front panel, external I/O operation setting

14.3.3.1. Filament operation setting "Fi"

Selects whether filament OFF is to be operated on the front panel or with external I/O. This function will be invalidated if it is set at RS-485 communication.

Display	Detail
"F"	Operation on the front panel only
"0"	Operation of external I/O only

14.3.3.2. Degas operation setting "dE"

Selects whether degassing ON/OFF is to be operated on the front panel or with external I/O. This function will be invalidated if RS-485 communication is set.

Display	Detail
"F"	Operation on front panel only
"0"	Operation of external I/O only

14.3.3.3. Filament changeover setting "FL"



Setting only filament1, if you used ST200-A/ST2-1

ST200-A/ST2-1 has only one filament. Setting only filament1.

Selects whether selection of filament 1/2 is to be operated on the front panel or with external I/O. This function will be invalidated if it is set at RS-485 communication.

Also the filament set on the front panel will be invalidated when operation is changed over to external I/O.

Display	Detail
"0"	Operation of external I/O only
"1"	Setting of filament 1
"2"	Setting of filament 2

14.3.3.4. Operation setting method

Press the program key to change over the set mode. Each press on the program key changes over the display as follows. If filament is on (local or remote), this unit cannot do filament setting, degas setting, and filament1/2 setting.



14.4. Connection with the Sensor Unit

The table below gives the pin assignment in connecting to the sensor unit.

- In connecting to the sensor unit, it is recommended to connect all pins below.
- * Connector for connection "SENSOR": D-sub 15pin connector pin, M2.6mm screw
- * Connector for connection "SH200-A/ST200-A/SH2-1/ST2-1": D-sub15 pin connector socket, M2.6mm screw

"SENSOR"	Description	Detail	Sensor unit
1	DC24V power supply	DC24V power supply to the sensor unit	1
2	Error signal	Error signal is input.	2
4	Emission valid ^{*1}	Emission valid is input	4
5	Filament off	Filament off signal is output.	5
6	Filament1/2 changeover ^{*3}	Outputs filament1/2 changeover signal.	6
-	FIL power monitor ^{*3}	Not used	7
8	Pressure signal input+	Pressure signal is input.	8
9	Power supply GND	Power supply GND to the sensor unit	9
13	Degas on	Degas on signal is output.	13
15	Pressure signal input-	Pressure signal is input.	15
Case	FG	Frame ground	Case

*1: The emission valid signal is a signal indicating that the emission current is flowing normally. If this signal is not input, the set point of the instrument will not operate.

- *2: Not use in ST200-A/ST2-1.
- *3: This unit cannot use. The filament power monitor signal is a function that outputs a signal as on (low) when the power supplied to the filament of SH200-A/ST200-A/SH2-1/ST2-1 has exceed the specified value range.

14.5. Connection with External Devices

- The table below gives the pin assignment in the connection to external devices.
- * Connector for connection "I/O": D-sub 15pin connector socket, M2.6mm screw

"I/O"	Description	Remarks
2	Error signal	Lo when actuated, DC30V _{MAX} , 50mA _{MAX} , 70mW
3	Setpoint1 actuating signal	Lo when actuated, DC30V _{MAX} , 50mA _{MAX} , 70mW
4	Emission valid	Lo when actuated, DC30V _{MAX} , 50mA _{MAX} , 70mW
5	Filament on	Actuated when shorted to GND
6	Filament1/2 changeover ^{*1}	Input a signal when selecting FIL2
7	Setpoint3 actuating signal	Lo when actuated, $DC30V_{MAX}$, $50mA_{MAX}$, $70mW$
8	Pressure signal output+	DC0V to 10V
9	Signal GND	GND of pressure signal, burnout signal, setpoint, etc.
10	RS485-	Serial communication RS485- output
11	Setpoint2 actuating signal	Lo when actuated, $DC30V_{MAX}$, $50mA_{MAX}$, $70mW$
12	RS485+	Serial communication RS485+ output
13	Degas on	Actuated when shorted to GND
15	Signal CND	GND of pressure signal, filament disconnect signal,
		setpoint, etc.
Case	FG	Frame ground

*1: Setting only firament1, if you used ST200-A/ST2-1.

14.6. Various Signals

14.6.1. Output voltage

The output voltage is output with + [8pin] of the I/O connector \rightarrow GND [15pin] P = 10 ^ { (V - 7.25) / 0.75 + k } × C

$$\longleftrightarrow V = 7.25 + 0.75 \times \{ \log (P/C) - k \}$$

P: Pressure value

V: Measurement value output voltage (V)

C: Calculation value (Refer to below table or section 18)

k: Conversion factor (Refer to the table below)

Measurement Unit	k	С
Pa	2	$1.0 \times 10^{+0}$
Torr	-0.1249	7.5×10^{-3}
mbar	0	1.0×10^{-2}

Operating state	Analog output voltage
During normal measurements	Voltage corresponding to the measured pressure 0.27V to 8.75V
1x10 ⁺⁴ Pa or higher	8.75V
SH200-A/ST200-A/SH2-1/ST2-1 gauge FIL OFF	Voltage corresponding to the measured by SPU 5V to 8.75V
SH200-A/ST200-A/SH2-1/ST2-1 error (Errors such as a filament disconnection)	Voltage corresponding to the measured by SPU 5V to 8.75V
SPU error (Errors such as a filament disconnection)	9.9V or higher
Power supply voltage abnormality, sensor unit fault, etc.	0.1V or less



14.6.2. Filament off signal

Signal that turns off the filament. When turning on the filament by operating with external I/O, connect to GND with an external switch. In the case of front panel operation or RS-485 communication setting, input of this signal will be invalid.

14.6.3. Degas on signal

Signal that turns on degassing. When turning on the degas by operating with external I/O, connect to GND with an external switch. In the case of front panel operation or RS-485 communication setting, input of this signal will be invalid.

14.6.4. Filament1/2 changeover signal

	Filament1/2 materials
	M-44/M-45/M-46: Both filament1 and filament2 are yttria-coated iridium wire
	M-34/M-35/M-36: Filament1 is a yttria-coated iridium wire. Filament2 is a tungsten wire.
CAUTION	Setting only filament1, if you used ST200-A/ST2-1 ST200-A/ST2-1 has only one filament. Setting only filament1.

Signal that changes over filament1/2. To change it over to filament2, connect it to GND. In the case of front panel operation or RS-485 communication setting, input of this signal will be invalid.

14.6.5. Sensor error signal

Sensor errors are signals that are output when an error occurs on sensor units.

When SH200-A/ST200-A/SH2-1/ST2-1 is error, this unit displays pressure of Pirani gauge. When Pirani gauge is error, this unit displays "Err".

When a sensor error occurs, the signal becomes low output

Photocoupler rating: DC30V_{MAX}, 50mA_{MAX}, 70mW

For more information about sensor error and actions in case of sensor error signal being turned on, refer to the sensor unit manual.

14.6.6. Emission valid signal

When the emission current is flowing normally or not is output as a signal. If emission current is flowing normally, the open collector will be Lo output.

Photocoupler rating: DC30V_{MAX}, 50mA_{MAX}, 70mW

If an emission error occurs during SH200-A/ST200-A/SH2-1/ST2-1measurement, it can be released by forcibly turning off the SH200-A/ST200-A/SH2-1/ST2-1 filament.

For details of this signal and what to do when this signal is turned off, refer to the instruction manual of the sensor unit.

14.6.7. Setpoint

For how to adjust and use the setpoint, refer to section 7. Photocoupler rating: $DC30V_{MAX}$, $50mA_{MAX}$, 70mW

14.6.8. RS-485 communication

For RS-485 communication, refer to section 22

15. Multi Ionization Gauge SH200-A/ST200-A/SH2-1/ST2-1 (SAU combination mode)

	The support model of SH2-1 becomes manufacturing numbers after
	<u>06001</u>
	If manufacturing number of SH2-1 is before 06001 , this unit may not output
	setpoints.
	The support model of ST2-1 becomes manufacturing numbers after
	<u>00901</u>
	If manufacturing number of ST2-1 is before 00901, this unit may not output
	setpoints.
	We recommended a connection with the analog output type
	When connecting to the serial communication type SH200-R/ST200-
	R/SH2-2/ST2-2, FIL ON, etc. cannot be performed with the sensor.
<u> </u>	Depending on the cable connection, there is a risk of damage to the multi
	ionization gauge SH200-R/ST200-R/SH2-2/ST2-2.
	ISG1 and SH200-A/ST200-A/SH2-1/ST2-1 connection cable
	The cable to connect the sensor and the SH200-A/ST200-A/SH2-1/ST2-1 has
	a maximum length of 40m for the 24AWG. To use the sensor with a cable
<u> </u>	longer than 40m, directly connect the SH200-A/ST200-A/SH2-1/ST2-1 to a
	power supply or increase the cable diameter.

This section describes the operation of the SH200-A/ST200-A/SH2-1/ST2-1 (SAU combination mode). Before reading this section, read the standard operating procedure in the foregoing sections.

15.1. Sensor Unit Setting: "SAU"

Turn on the power to this unit and make sure that "SAU" lights for several seconds.

To display others, press the \bigcirc key several times within 3sec after turning on power, change the display to "SAU" and make it definite with the \bigcirc key.

For more information about the sensor unit setting, refer to section 6.

15.2. Front Panel

15.2.1. Pressure display

Status	Pressure indicator	LED	
In normal measurement	5.0×10^{-8} Pa to $1.0 \times 10^{+5}$ Pa		
Below measurement pressure range	0.0×10 ⁻⁸ Pa		
Above measurement pressure range	F.F×10 ^{+F} Pa		
When error of SH200-A/ST200-A/SH2-1/ST2-1	Pressure indication more	Err I ED lights	
(When error signal is input)	than 1.0×10 ⁻¹ Pa	EII LED lights	
When error of SWU10-R/SPU	Pressure indication more	Err I ED lights	
(When error signal is input)	than 1.0×10 ⁺⁴ Pa	Err LED lights	
When error of SWU10-R/SPU	Err	Err I ED lights	
(When error signal is input)	(Setpoints off)	EII LED lights	
When error of SAU	Err	Err LED off	
(When error signal is not input)	(Setpoints off)	EII LED OII	
SH200 Λ /ST200 Λ /SH2 1/ST2 1 emission valid off ^{*1}	Display is pressure	Err LED	
511200-A/51200-A/5112-1/512-1 emission vand on	(Setpoints off)	blinking	
When SH200-A/ST200-A/SH2-1/ST2-1 degassing is	Prossure indication	DEG LED	
on	riessure indication	lights	
SU200 A/ST200 A/SU2 1/ST2 1 EIL OEE	Pressure indication more	ZERO LED	
Sn200-A/S1200-A/Sn2-1/S12-1 FIL OFF	than 1.0×10 ⁻¹ Pa	lights	

*1: However, the error of SH200-A/ST200-A/SH2-1/ST2-1 is cleared by turning FIL off (Forced FIL OFF).

*: When a CALCULATION function is used, it displays to 10⁻¹¹ at the minimum. 10⁻¹⁰ is "A (A of capital letter)", 10⁻¹¹ is "b (B of small letter)". Please note "b (B of small letter)" to make a mistake as '6' of the figure.

15.2.2. Description of front panel keys

Inscription	Function	Remarks
PROG	Enters into program mode	Refer to section 5 and this section
ZERO	Not used	
DEG	Degassing ON/OFF operation	Cannot be operated when RS485 and external I/O are set
FIL	Filament off operation	Cannot be operated when RS485 and external I/O are set

15.3. Setting Operation

15.3.1. Setting overview

The following settings are available for turning on the filament or degassing and for changing over the filament 1/2.

Setting	Overview
RS-485 communication mode	Only RS-485 communication is available.
Front panel operation mode	Only front panel operation is available.
External I/O operation mode	Only external I/O operation is available

15.3.2. RS-485 communication operation setting "L1", "L2"

Selects if filament OFF, degassing ON/OFF or filament1/2 changeover is to be operated through RS-485 communication. Refer to section 22 for more information about the detailed setting of RS-485.

Display	Details	Remarks
"L1"	Operation on the front panel and external I/O	RS-485: Pressure reading only
"L2" Only operation through RS-485 communication		

15.3.3. Front panel, external I/O operation setting

15.3.3.1. Filament operation setting "Fi"

Selects whether filament off is to be operated on the front panel or with external I/O. This function will be invalidated if it is set at RS-485 communication.

Display	Detail
"F"	Operation on the front panel only
"0"	Operation of external I/O only

15.3.3.2. Degas operation setting "dE"

Selects whether degassing ON/OFF is to be operated on the front panel or with external I/O. This function will be invalidated if RS-485 communication is set.

Display	Detail
"F"	Operation on front panel only
"0"	Operation of external I/O only

15.3.3.3. Filament changeover setting "FL"

Setting only filament1, if you used ST200-A/ST2-1

ST200-A/ST2-1 has only one filament. Setting only filament1.

Selects whether selection of filament1/2 is to be operated on the front panel or with external I/O. This function will be invalidated if it is set at RS-485 communication.

Also the filament set on the front panel will be invalidated when operation is changed over to external I/O.

Display	Detail
"0"	Operation of external I/O only
"1"	Setting of filament1
"2"	Setting of filament2

15.3.3.4. Operation setting method

Press the program key to change over the set mode. Each press on the program key changes over the display as follows. If filament is on (local or remote), this unit cannot do filament setting, degas Setting, and filament1/2 setting.



15.4. Connection with the Sensor Unit

The table below gives the pin assignment in connecting to the sensor unit.

- In connecting to the sensor unit, it is recommended to connect all pins below.
- * Connector for connection "SENSOR": D-sub 15pin connector pin, M2.6mm screw
- * Connector for connection "SH200-A/ST200-A/SH2-1/ST2-1": D-sub 15pin connector socket, M2.6mm screw

"SENSOR"	Description	Detail	Sensor unit
1	DC24V power supply	DC24V power supply to the sensor unit	1
2	Error signal	Error signal is input.	2
4	Emission valid ^{*1}	Emission valid is input	4
5	Filament on	Filament on signal is output.	5
6	Filament1/2 changeover ^{*2}	Outputs filament1/2 changeover signal.	6
-	FIL power monitor ^{*3}	Not use	7
8	Pressure signal input	Pressure signal is input.	8
9	Power supply GND	Power supply GND to the sensor unit	9
13	Degas on	Degas on signal is output.	13
15	GND	GND of pressure signal and each signal	15
Case	FG	Frame ground	Case

*1: The emission valid signal is a signal indicating that the emission current is flowing normally. If this signal is not input, the set point of the instrument will not operate.

- *2: Not use in ST200-A/ST2-1.
- *3: This unit cannot use. The filament power monitor signal is a function that outputs a signal as on (low) when the power supplied to the filament of SH200-A/ST200-A/SH2-1/ST2-1 has exceed the specified value range.

15.5. Connection with External Devices

- The table below gives the pin assignment in the connection to external devices.
- * Connector for connection "I/O": D-sub 15pin connector socket, M2.6mm screw

"I/O"	Description	Remarks
2	Error signal	Lo when actuated, DC30V _{MAX} , 50mA _{MAX} , 70mW
3	Setpoint1 actuating signal	Lo when actuated, DC30V _{MAX} , 50mA _{MAX} , 70mW
4	Emission valid	Lo when actuated, DC30V _{MAX} , 50mA _{MAX} , 70mW
5	Filament on	Actuated when shorted to GND
6	Filament1/2 changeover ^{*1}	Input a signal when selecting FIL2
7	Setpoint3 actuating signal	Lo when actuated, $DC30V_{MAX}$, $50mA_{MAX}$, $70mW$
8	Pressure signal output+	DC0V to 10 V
9	Signal GND	GND of pressure signal, burnout signal, setpoint, etc.
10	RS485-	Serial communication RS-485- output
11	Setpoint2 actuating signal	Lo when actuated, $DC30V_{MAX}$, $50mA_{MAX}$, $70mW$
12	RS485+	Serial communication RS-485+ output
13	Degas ON	Actuated when shorted to GND
15	GND	GND of pressure signal, burnout signal, setpoint, etc.
Case	FG	Frame ground

*1: Setting only firament1, if you used ST200-A/ST2-1.
15.6. Various Signals

15.6.1. Output voltage

The output voltage is output with + [8pin] of the I/O connector \rightarrow GND [15pin] P = 10 ^ { (V - 7.25) / 0.75 + k } \times C

$$\longleftrightarrow V = 7.25 + 0.75 \times \{ \log (P/C) - k \}$$

P: Pressure value

V: Measurement value output voltage (V)

C: Calculation value (Refer to section18)

k: Conversion factor (Refer to the table below)

Measurement Unit	k
Ра	2
Torr	-0.1249
mbar	0

Operating state	Analog output voltage	
During normal measurements	/oltage corresponding to the measured pressure 0.27V to 9.5V	
Atmospheric pressure or higher	9.5V	
SH200-A/ST200-A/SH2-1/ST2-1 FIL OFF	Voltage corresponding to the measured by SWU/SPU and SAU 5V to 9.5V	
SH200-A/ST200-A/SH2-1/ST2-1 error (Errors such as a filament break)	Voltage corresponding to the measured by SWU/SPU and SAU 5V to 9.5V	
SWU/ SPU error (Errors such as a filament break)	Voltage corresponding to the measured by SAU 8.677V to 9.5V	
SAU error (Errors such as a filament break)	9.9V or higher	
Power supply voltage abnormality, sensor unit fault, etc.	0.1V or less	



15.6.2. ilament off signal

Signal that turns off the filament. When turning on the filament by operating with external I/O, connect to GND with an external switch. In the case of front panel operation or RS-485 communication setting, input of this signal will be invalid.

15.6.3. Degas on signal

Signal that turns on degassing. When turning on the degas by operating with external I/O, connect to GND with an external switch. In the case of front panel operation or RS-485 communication setting, input of this signal will be invalid.

15.6.4. Filament1/2 changeover signal

Filament1/2 materials
M-44/M-45/M-46: Both filament1 and filament2 are yttria-coated iridium
wire.
M-34/M-35/M-36: Filament1 is a yttria-coated iridium wire.
Filament2 is a tungsten wire.
Setting only filament1, if you used ST200-A/ST2-1
ST200-A/ST2-1 has only one filament. Setting only filament1.

Signal that changes over filament1/2. To change it over to filament2, connect it to GND. In the case of front panel operation or RS-485 communication setting, input of this signal will be invalid.

15.6.5. Sensor error signal

Sensor errors are signals that are output when an error occurs on sensor units.

When SH200-A/ST200-A/SH2-1/ST2-1 is error, this unit displays pressure of Pirani gauge. When Pirani gauge is error, this unit displays "Err"

When a sensor error occurs, the signal becomes low output.

Photocoupler rating: DC30V_{MAX}, 50mA_{MAX}, 70mW

For more information about sensor error and actions in case of sensor error signal being turned on, refer to the sensor unit manual.

15.6.6. Emission valid signal

When the emission current is flowing normally or not is output as a signal. If emission current is flowing normally, the open collector will be Lo output.

Photocoupler rating: DC30V_{MAX}, 50mA_{MAX}, 70mW

If an emission error occurs during SH200-A/ST200-A/SH2-1/ST2-1measurement, it can be released by forcibly turning off the SH200-A/ST200-A/SH2-1/ST2-1 filament.

For details of this signal and what to do when this signal is turned off, refer to the instruction manual of the sensor unit.

15.6.7. Setpoint

For how to adjust and use the setpoint, refer to section 7. Photocoupler rating: DC30V_{MAX}, 50mA_{MAX}, 70mW

15.6.8. RS-485 communication

For RS-485 communication, refer to section 22.

16. MULTI IONIZATION GAUGE SH200-A/ST200-A/SH2-1/ST2-1 (SWU combination mode)

	The support model of SH2-1 becomes manufacturing numbers after
	<u>06001</u>
	If manufacturing number of SH2-1 is before 06001, this unit may not
	output setpoints.
	The support model of ST2-1 becomes manufacturing numbers after
	<u>00901</u>
	If manufacturing number of ST2-1 is before 00901, this unit may not output
	setpoints.
	We recommended a connection with the analog output type
	When connecting to the serial communication type SH200-R/ST200-R/SH2-
	2/ST2-2, FIL ON, etc. cannot be performed with the sensor. Depending on
	the cable connection, there is a risk of damage to the multi ionization gauge
	SH200-R/ST200-R/SH2-2/ST2-2.
	Sensor and SH200-A/ST200-A/SH2-1/ST2-1 connection cable
	The cable to connect the sensor and the SH200-A/ST200-A/SH2-1/ST2-1 has
/1 \CAUTION	a maximum length of 40m for the 24AWG. To use the sensor with a cable
	longer than 40m, directly connect the SH200-A/ST200-A/SH2-1/ST2-1 to a
	power supply or increase the cable diameter.

This section describes the operation of the SH200-A/ST200-A/SH2-1/ST2-1 (SWU combination mode). Before reading this section, read the standard operating procedure in the foregoing sections.

16.1. Sensor Unit Setting: "SAU"

Turn on the power to this unit and make sure that "SAU" lights for several seconds.

To display others, press the \bigcirc key several times within 3sec after turning on power, change the

- display to "SAU" and make it definite with the \checkmark key. For more information about the sensor unit setting, refer to Section 6.
- 16.2. Front Panel
- 16.2.1. Pressure display

Status	Pressure indicator	LED	
In normal measurement	5.0×10^{-8} Pa to $1.0 \times 10^{+5}$ Pa		
Below measurement pressure range	0.0×10 ⁻⁸ Pa		
Above measurement pressure range	F.F×10 ^{+F} Pa		
When error of SH200-A/ST200-A/SH2-1/ST2-1	Pressure indication more than	Err I ED lights	
(When error signal is input)	1.0×10 ⁻¹ Pa	EIT LED lights	
When error of SWU	Err	En IED lights	
(When error signal is input)	(Setpoints off)	EII LED lights	
When error of SWU	Err		
(When error signal is not input)	(Setpoints off)		
SH200 A/ST200 A/SH2 1/ST2 1 emission valid OFE *1	Display is pressure	Err LED	
SH200-A/S1200-A/SH2-1/S12-1 emission vand OFT	(Setpoints off)	blinking	
When SH200-A/ST200-A/SH2-1/ST2-1 degassing is on	Pressure indication	DEG is lit	
SH200 A/ST200 A/SH2 1/ST2 1 EIL off	Pressure indication more than		
11200-A/51200-A/5112-1/512-1 I'IL 011	1.0×10 ⁻¹ Pa		

*1: However, the error of SH200-A/ST200-A/SH2-1/ST2-1 is cleared by turning FIL off (Forced FIL OFF).

*: When a CALCULATION function is used, it displays to 10⁻¹¹ at the minimum. 10⁻¹⁰ is "A (A of capital letter)", 10⁻¹¹ is "b (B of small letter)". Please note "b (B of small letter)" to make a mistake as '6' of the figure.

16.2.2. Description of front panel keys

Inscription	Function	Remarks	
PROG	Enters into program mode	Refer to section 5 and this section	
ZERO	Not used		
DEG	Degassing ON/OFF operation	Cannot be operated when RS485 and external I/O are set	
FIL	Filament off operation	Cannot be operated when RS485 and external I/O are set	

16.3. Setting Operation

16.3.1. Setting overview

The following settings are available for turning on the filament or degassing and for changing over the filament 1/2.

Setting	Overview
RS-485 communication mode	Only RS-485 communication is available
Front panel operation mode	Only front panel operation is available
External I/O operation mode	Only external I/O operation is available

16.3.2. RS-485 communication operation setting "L1", "L2"

Selects if filament off, degassing ON/OFF or filament1/2 changeover is to be operated through RS-485 communication. Refer to section 22 for more information about the detailed setting of RS-485.

Display	Details	Remarks
"L1"	Operation on the front panel and external I/O	RS-485: Pressure reading only
"L2" Only operation through RS-485 communication		

16.3.3. Front panel, external I/O operation setting

16.3.3.1. Filament operation setting "Fi"

Selects whether filament OFF is to be operated on the front panel or with external I/O. This function will be invalidated if it is set at RS-485 communication.

Display	Detail
"F"	Operation on the front panel only
"0"	Operation of external I/O only

16.3.3.2. Degas operation setting "dE"

Selects whether degassing ON/OFF is to be operated on the front panel or with external I/O. This function will be invalidated if RS-485 communication is set.

Display	Detail	
"F"	Operation on front panel only	
"0"	Operation of external I/O only	

16.3.3.3. Filament changeover setting "FL"



Setting only filament1, if you used ST200-A/ST2-1 ST200-A/ST2-1 has only one filament. Setting only filament1.

Selects whether selection of filament1/2 is to be operated on the front panel or with external I/O. This function will be invalidated if it is set at RS-485 communication.

Also the filament set on the front panel will be invalidated when operation is changed over to external I/O.

Display	Detail	
"0"	Operation of external I/O only	
"1"	Setting of filament1	
"2"	Setting of filament2	

16.3.3.4. Operation setting method

Press the program key to change over the set mode. Each press on the program key changes over the display as follows. If filament is on (local or remote), this unit cannot do filament setting, degas setting, and filament1/2 setting.



16.4. Connection with the Sensor Unit

The table below gives the pin assignment in connecting to the sensor unit.

- In connecting to the sensor unit, it is recommended to connect all pins below.
- * Connector for connection "SENSOR": D-sub 15pin connector pin, M2.6mm screw
- * Connector for connection "SH200-A/ST200-A/SH2-1/ST2-1": D-sub15pin connector socket, M2 6mm screw

	W12:0hilli Sele w		
"SENSOR"	Description	Detail	Sensor unit
1	DC24V power supply	DC24V power supply to the sensor unit	1
2	Error signal	Error signal is input.	2
4	Emission valid ^{*1}	Emission valid is input	4
5	Filament off	Filament off signal is output.	5
6	Filament1/2 changeover ^{*2}	Outputs filament1/2 changeover signal.	6
-	FIL power monitor ^{*3}	Not used	7
8	Pressure signal input+	Pressure signal is input.	8
9	Power supply GND	Power supply GND to the sensor unit	9
13	Degas on	Degas on signal is output.	13
15	Pressure signal input-	Pressure signal is input.	15
Case	FG	Frame ground	Case

*1: The emission valid signal is a signal indicating that the emission current is flowing normally. If this signal is not input, the set point of the instrument will not operate.

- *2: Not use in ST200-A/ST2-1.
- *3: This unit cannot use. The filament power monitor signal is a function that outputs a signal as on (low) when the power supplied to the filament of SH200-A/ST200-A/SH2-1/ST2-1 has exceed the specified value range.

16.5. Connection with External Devices

- The table below gives the pin assignment in the connection to external devices.
- * Connector for connection "I/O": D-sub 15pin connector socket, M2.6mm screw

"I/O"	Description	Remarks	
2	Error signal	Lo when actuated, DC30V _{MAX} , 50mA _{MAX} , 70mW	
3	Setpoint1 actuating signal	Lo when actuated, DC30V _{MAX} , 50mA _{MAX} , 70mW	
4	Emission valid	Lo when actuated, DC30V _{MAX} , 50mA _{MAX} , 70mW	
5	Filament on	Actuated when shorted to GND	
6	Filament1/2 changeover ^{*1}	Input a signal when selecting FIL2	
7	Setpoint3 actuating signal	Lo when actuated, DC 30VDC _{MAX} , 50mA _{MAX} , 70mW	
8	Pressure signal output+	DC0V to 10V	
9	Signal GND	GND of pressure signal, burnout signal, setpoint, etc.	
10	RS485-	Serial communication R-S485- output	
11	Setpoint2 actuating signal	Lo when actuated, $DC30V_{MAX}$, $50mA_{MAX}$, $70mW$	
12	RS485+	Serial communication RS-485+ output	
13	Degas on	Actuated when shorted to GND	
15	Signal GND	GND of pressure signal, burnout signal, setpoint, etc.	
Case	FG	Frame ground	

*1: Setting only firament1, if you used ST200-A/ST2-1.

16.6. Various Signals

16.6.1. Output voltage

The output voltage is output with + [8pin] of the I/O connector \rightarrow GND [15pin] P = 10 ^ { (V - 7.25) / 0.75 + k } × C

$$\longleftrightarrow V = 7.25 + 0.75 \times \{ \text{ log (} P / C \text{) - } k \}$$

P: Pressure value

V: Measurement value output voltage (V)

C: Calculation value (Refer to blow table or section 18)

k: Conversion factor (Refer to the table below)

Measurement Unit	k	С
Ра	2	$1.0 \times 10^{+0}$
Torr	-0.1249	7.5×10^{-3}
mbar	0	1.0×10^{-2}

Operating state	Analog output voltage
During normal measurements	Voltage corresponding to the measured pressure 0.27V to 9.5V
Atmospheric pressure or higher	9.5V or higher
SH200-A/ST200-A/SH2-1/ST2-1 FIL OFF	Voltage corresponding to the measured by SWU 5V to 9.5V
SH200-A/ST200-A/SH2-1/ST2-1 error	Voltage corresponding to the measured by SWU
(Errors such as a filament break)	5V to 9.5V
SWU error	0.0V or higher
(Errors such as a filament break)	9.9 V OI IIIghei
Power supply voltage abnormality,	0.1V or less
sensor unit fault, etc.	0.1 V 01 1055



16.6.2. Filament off signal

Signal that turns off the filament. When turning on the filament by operating with external I/O, connect to GND with an external switch. In the case of front panel operation or RS-485 communication setting, input of this signal will be invalid.

16.6.3. Degas on signal

Signal that turns on degassing. When turning on the degas by operating with external I/O, connect to GND with an external switch. In the case of front panel operation or RS-485 communication setting, input of this signal will be invalid.

16.6.4. Filament 1/2 changeover signal

	Filament1/2 materials
A	M-44/M-45/M-46: Both filament1 and filament2 are yttria-coated iridium
	wire.
	M-34/M-35/M-36: Filament1 is a yttria-coated iridium wire.
	Filament2 is a tungsten wire.
	Setting only filament1, if you used ST200-A/ST2-1
	ST200-A/ST2-1 has only one filament. Setting only filament1.

Signal that changes over filament1/2. To change it over to filament2, connect it to GND. In the case of front panel operation or RS-485 communication setting, input of this signal will be invalid.

16.6.5. Sensor error signal

Sensor errors are signals that are output when an error occurs on sensor units.

When SH200-A/ST200-A/SH2-1/ST2-1 is error, this unit displays pressure of Pirani gauge. When Pirani gauge is error, this unit displays "Err"

When a sensor error occurs, the signal becomes low output

Photocoupler rating: DC30V_{MAX}, 50mA_{MAX}, 70mW

For more information about sensor error and actions in case of sensor error signal being turned on, refer to the sensor unit manual.

16.6.6. Emission valid signal

When the emission current is flowing normally or not is output as a signal. If emission current is flowing normally, the open collector will be Lo output.

Photocoupler rating: DC30V_{MAX}, 50mA_{MAX}, 70mW

If an emission error occurs during SH200-A/ST200-A/SH2-1/ST2-1measurement, it can be released by forcibly turning off the SH200-A/ST200-A/SH2-1/ST2-1 filament.

For details of this signal and what to do when this signal is turned off, refer to the instruction manual of the sensor unit.

16.6.7. Setpoint

For how to adjust and use the setpoint, refer to section 7. Photocoupler rating: DC30V_{MAX}, 50mA_{MAX}, 70mW

16.6.8. RS-485 communication

For RS-485 communication, refer to Section 22.

17. CCM SERIES CERAMIC CAPASITANCE MANOMETER

This section describes the operation of the CCMT-A series, CCMT-D series and CCMH-A series ceramic capacitance manometers.

Before reading this section, read the standard operating procedure in the preceding sections.

17.1. Sensor Unit Setting

Turn on the power to this unit and make sure that the following display lights for several seconds. For display of others, change the setting as shown below, referring to section 6.

Display	Sensor unit		
Cn3	CCMT-1000A	CCMT-1000D	CCMH-1000A
Cn2	CCMT-100A	CCMT-100D	CCMH-100A
Cn1	CCMT-10A	CCMT-10D	CCMH-10A
Cn0	-	CCMT-1D	CCMH-1A

17.2. Front Panel Display

17.2.1. Pressure display

State	Pressure indicator	LED
In normal measurement	$0.0 \times 10^{+N-4}$ Pa to $1.3 \times 10^{+N}$ Pa	ZERO LED lights/off
Below measurement pressure range	Display by blinking	ZERO LED lights/off
Above measurement pressure range	FFF	ZERO LED lights/off
When zero point adjustment is completed	$0.0 \times 10^{+N-4} \text{ Pa}$	ZERO LED lights
When zero point adjustment is reset	Pressure indication	ZERO LED lights
When sensor unit is not connected		Err LED lights

Sensor Unit	Ν
CCMT-1000A/1000D、CCMH-1000A	5
CCMT-100A/100D、CCMH-100A	4
CCMT-10A/10D、CCMH-10A	3
CCMT-1D、CCMH-1A	2

17.2.2. Front panel operation

Inscription	Function	Remarks	
PROG	Enters into the program mode	Refer to Section 5 and this section.	
ZERO	Makes zero point adjustment	Cannot be operated when RS-485 and I/O are set	
DEG	Not used		
FIL	Not used		

17.3. Operation setting

For adjustment of the zero point, the following settings are available.

Setting	Overview
Front panel operation mode	Only operation on front panel is possible
External I/O operation mode	Only external I/O can be operated
RS-485 communication mode	Only RS-485 communication can be operated

17.3.1. RS-485 communication operation setting "L1", "L2"

Selects whether RS-485 communication is to be used or not.

Refer to section 22 for the detailed setting of RS-485.

Display	Detail	Remarks
"L1"	Operation on the front panel or external I/O	RS-485:Pressure reading only
"L2"	Only RS-485 communication can be operated	

17.3.2. Front panel and external I/O operation setting "AJ"

Selects whether execution of zero point adjustment is to be made on the front panel or by external I/O.

Display	Detail
"F"	Operation on front panel only
"O"	Operation of I/O only

17.3.3. Setting method

Press the **PROG** key to change over the setting mode. Each press on the program key changes the display as follows.

Pres	sure display <	
	PROG	
	$\begin{array}{c} \textbf{ST1 setting: ST1 LED blinks} & \longrightarrow & \textbf{Change the setting} \\ \hline \textbf{PROG} \end{array}$	· · · · · · · · · · · · · · · · · · ·
49-	ST2 setting: ST2 LED blinks \longrightarrow Change the setting \bigtriangleup \bigcirc PROG	· []
49-	ST3 setting: ST3 LED blinks \longrightarrow Change the setting \bigtriangleup \bigcirc PROG	· []
	Calculation setting: \longrightarrow Change the setting \bigtriangleup PROG	· []
	RS485 setting: Display "L1" or "L2" \longrightarrow determined by the setting det	ermine
	$ \square $	
	determine	
	Interlock setting: \longrightarrow Change the setting \bigtriangleup \bigcirc) (J)
↓ ⊔ 	$\begin{array}{c} \text{Measurement units setting} & \longrightarrow & \text{Change the setting} \\ \hline \\ $	· [] []
F	Measurement display range setting \longrightarrow Change the setting \square PROG	· 신
	I Setting sensor: Displayed Image: Image	ermine
	ZERO point adjustment setting: Display "AJ"	ermine
	$ \rightarrow \square $ $ h $ or $ o $ blinks	
	determine	

17.4. Connection to Sensor Unit

The table below gives pin assignment in the connection with the sensor unit. It is recommended to connect all of the following pins in connecting to the sensor unit.

Connector for connection "SENSOR": D-sub 15pin connector male, M2.6mm screw
Connector for connection "CCM": D-sub 15pin connector female, M2.6mm screw

"SENSOR"	Description	Remarks	Sensor unit
1	24VDC power supply	24VDC power supply to sensor unit	11
8	Pressure signal input+	Pressure signal is input	2
9	Power supply GND	Power GND to the sensor unit	5
15	Pressure signal input-	Pressure signal is input	12
Case	FG	Frame ground	Case

17.5. Connection to external device

The table below gives the pin assignment in connecting to external device.

* Connector for connection "I/O": D-sub 15pin connector female, M2.6mm screw

"I/O"	Description	Remarks	
3	Setpoint1 actuating signal	Lo when actuated, 30VDC _{MAX} , 50mA _{MAX} , 70mW	
7	Setpoint3 actuating signal	Lo when actuated, 30VDC _{MAX} , 50mA _{MAX} , 70mW	
8	Pressure signal output+	0V to 10VDC	
9	Signal GND	GND of pressure signal, burnout signal, setpoint, etc.	
10	RS485-	Serial communication RS-485- output	
11	Setpoint2 actuating signal	Lo when actuated, 30VDC _{MAX} , 50mA _{MAX} , 70mW	
12	RS485+	Serial communication RS-485+ output	
15	Signal GND	GND of pressure signal, burnout signal, setpoint, etc.	
Case	FG	Frame ground	

17.6. Signals

17.6.1. Output voltage

Output voltage is output from +[pin8] of the I/O connector to GND [pin15].

 $\mathbf{P} = \mathbf{V} \times \mathbf{k} \times \mathbf{C} \times \mathbf{m} \quad \boldsymbol{\leftarrow} \rightarrow \quad \mathbf{V} = \mathbf{P} \ / \ \mathbf{k} \ / \ \mathbf{C} \ / \ \mathbf{m}$

P: Pressure value

V: Measurement value output voltage (V)

C: Calculation value (Refer to below table or section 18)

k: Conversion factor (Refer to the table below)

m: Factor of sensor type (Refer to the table below)

m	Type of sensor		
1000	CCMT-1000A	CCMT-1000D	CCMH-1000A
100	CCMT-100A	CCMT-100D	CCMH-100A
10	CCMT-10A	CCMT-10D	CCMH-10A
1		CCMT-1D	CCMH-1A

Measurement unit	k	С
Pa	13.33	$1.0 imes 10^{+0}$
Torr	0.1	7.5×10 ⁻³
mbar	0.1333	1.0×10^{-2}

State	Measurement value output voltage	Remarks
In normal measurement	Voltage corresponding to measured	
In normal measurement	pressure	
Above measurable	10 V	The display is "FFF"
higher limit	10 V	The display is TTT.
Below measurable lower	0 V	The display blipks
limit	U V	The display blinks.



- 17.6.2. Setpoint
 - Refer to section 7 for how to adjust and use the setpoint. Photocoupler rating: 30V_{MAX}, 50mA_{MAX}, 70mW
- 17.6.3. RS-485 communication

Refer to section 22 for RS-485 communication.

17.7. ZERO Point Adjustment

Zero point can be adjusted by the unit for ceramic capacitance manometer setting. It can be done from the front panel, external I/O, or RS485.

ZERO point adjustment range: Voltage from sensor unit = within ± 20 mV

Pressure value = within $\pm 2.6 \times 10^{+N-3}$ Pa

*An error will occur if adjustment cannot be made within the above adjustment range. In that case, execute "zero point reset" and then perform zero point adjustment on the sensor unit. Refer to Sections 17.7.1, 17.7.2, and 17.7.3 for how to execute "zero point reset", and to the instruction manual for the sensor unit for how to perform zero point adjustment on the sensor unit.

17.7.1. Operation front panel

ZERO point adjustment: Hold down the "ZERO" switch for 1sec or more. ZERO point reset : Hold down the "ZERO" switch for 3sec or more.

17.7.2. Operation external I/O

ZERO point adjustment: Turn on (short) "ZERO" from I/O for 1sec or more ZERO point reset : Turn on (short) "ZERO" from I/O for 3sec or more

17.7.3. RS-485 communication Refer to section 22 for RS-485 communication.

18. CALCULATING FUNCTION

$$\underbrace{\frac{\text{Display of 10^{-10}, 10^{-11}}}{10^{-10} \text{ is "A (A of capital letter)", 10^{-11} is "b (B of small letter)".}}_{\text{Please note "b (B of small letter)" to make a mistake as '6' of the figure.}}$$

CALCULATION function (Hereafter, it abbreviates to CAL) powers desired value (from 1.0×10^{-10}

 $^{3}\sim$ 1.0×10⁺³) to the measured pressure value, and reflect to the display unit.

This function is used to set the specific sensitivity of the gas in the hot cathode ionization vacuum gauge and to switch the pressure unit for display.

18.1. Display Pressure Value in CAL Function

Displayed pressure value = Actual measured pressure \times CAL set value

Please be aware that not only the displayed pressure value, but also the output voltage changes. 10^{-10} is "A (A of capital letter)", 10^{-11} is "b (B of small letter)". Please note "b (B of small letter)" to make a mistake as '6' of the figure.

- 18.2. Output voltage in CAL function mode Please refer to each chapter.
- 18.3. Setting CAL value





Setting sensor, etc



- 18.4. Specific Sensitivity Value of Gas in Hot Cathode Ionization Gauge Please refer to each manual.
- 18.5. CAL Value of Measurement Unit

measurement unit	CAL value
Pa	$1.0 \times 10^{+0}$
Torr	7.5×10 ⁻³
mbar	1.0×10 ⁻²

19. INTERLOCK FUNCTION

This function locks the front panel button controls, under certain condition.

19.1. Interlock Setting Interlock setting can only be changed from the front panel control.

Method	Operation
Setting	PROG, set the interlock "In" to "o"
Unlocking	Hit any key on the front panel while displaying the pressure value so that the numbers start blinking. Hold PROG more than 5sec after the blink, in order to reset the interlock.

Display	Detail
"F"	Off interlock state
"o"	Interlock is on

Pressure display, etc.
$ 4 \underline{\mathcal{G}}^{-2} \text{ ST1 setting: SET-1 LED blinks} \text{Change the setting } {PROG} $
$\begin{array}{c} & \swarrow \\ & \swarrow \\ & \blacksquare \end{array} \xrightarrow{?} ST2 \text{ setting: SET-2 LED blinks} \longrightarrow Change the setting \bigcirc \\ & \bigcirc \\ & \square \end{array} \xrightarrow{?} PROG \end{array}$
$\mathcal{U} \stackrel{\checkmark}{=} \mathcal{Z} \text{ ST3 setting: SET-3 LED blinks} \longrightarrow \text{ Change the setting } \bigcirc $
$ \begin{array}{c c} & & & \\ $
$ \begin{array}{c ccccccccccccccccccccccccccccccccccc$
$ \begin{array}{c} & & \\ & & $
$ \begin{array}{c} & & \\ & & $
Setting sensor: Displayed setting the sensor \longrightarrow \swarrow determine \longrightarrow
Setting of sensor Change the setting ▷ ▷ ⊘

20. MEASUREMENT UNITS FUNCTION

20.1. Measurement Units Setting

Measurement unis setting can only be changed from the front panel control.

method		Operation
Setting	PROG, set the measur	rement units "un" to "P", "t" or "b"
	Display "P" "t" "b"	Detail Pa Torr mbar
$ \begin{array}{c} \text{Pressure dis} \\ & & \\ & & \\ \hline \\ PROG \\ \hline \\ & & \\ \hline \\ PROG \end{array} \end{array} $	play, etc. <] etting: SET-1 LED blinks —]	\longrightarrow Change the setting \bigcirc \bigcirc \bigcirc
¥ <u></u> g-² ST2 s PROG	etting: SET-2 LED blinks —]	$\longrightarrow \text{ Change the setting } \bigcirc $
$\mathcal{U} \stackrel{\forall}{=} \mathcal{Z} ST3 s$	etting: SET-3 LED blinks —	$\longrightarrow \text{ Change the setting } \bigcirc $
$\begin{bmatrix} \overset{\vee}{H} & L \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\ \\$	lation settinmg:	$\longrightarrow \text{ Change the setting } \bigcirc \bigcirc $
RS48	5 setting: Display "L1" or "I	L2" \longrightarrow Change the setting \bigcirc \bigcirc \bigcirc
Interle	ock settinmg	$\longrightarrow \text{ Change the setting } $
₩ Meass PROG	urement units setting \downarrow \bigcirc "P", \downarrow \bigcirc Sele \downarrow \bigcirc determined	→ Change the setting ▷ ि , "t" or "b" blinks ect "P", "t" or "b" ermine
PRO	urement display range settin G	$hg \longrightarrow$ Change the setting \square \square \square
$ \begin{array}{c} \overset{\vee}{\scriptstyle$	or: Displayed setting the sen	nsor> 🖓 determine
Setting of se	nsor	$\longrightarrow \text{ Change the setting } \bigcirc \bigcirc $

21. MEASUREMENT DISPLAY RANGE SETTING

The pressure measurement display setting is the function which sets the range which measurement of the pressure. Indication lower than the lower limit which isn't indicated beyond the upper limit value isn't done.

21.1. Measurement display Range rA Setting







22. RS-485

	Caution in laying cables
	When laying transmission lines for communication in the unit, see to it
	that they are not in the proximity of, or parallel to, the power line, high
	voltage line, high frequency line, etc. Failure to comply with this caution
	can cause malfunction.
A	Remote host
/1 \CAUTION	Use a noise-immune isolation for the remote host like PC, sequencer, etc.
	Otherwise, malfunction or failure can result.

This section describes how to set and use RS-485.

22.1. Communication Specifications

22.1.1. Standard specifications	
Two-wire system	
Half duplex	
Start-stop synchronization system	
ASCII code	
Transmission distance	1200m*
Maximum number of connections	32 (including host)
Baud rate	9600/19200/38400 bps

*: Maximum cable length is 1200m in the RS-485 standard. Please check a specification of remote host and an environmental noise if you use the cable of 30m or more.

22.1.2. Communication setting

DATA	 8 bits
Parity	None
Stopbit	1 bit

* Change over the mode to the receiving state within 20msec after sending data.

- * Set the time-out before receiving data at 150msec or more.
- * After receiving data, send the next data with an interval of 50msec or more.

22.2. Setting

22.2.1. RS-485 communication setting "L2"

To use RS-485, it is necessary to set communication at "L2".

Display	Detail
"L1"	Operation on front panel external I/O.
"L2"	Only RS-485 is operated.

22.2.2. Baud rate setting

The table below gives the baud rate settings.

Display	Detail
960	9600 bps
192	19200 bps
384	38400 bps

22.2.3. Address setting

Address can be set from 01 to 32.

- * Note that remote host may be allocated to 00.
- * The maximum number of nodes is 32 per line, including the host.
- * Settings are validated as and when necessary.

22.2.4. Setting the checksum collating function

Checksum collating function checks if all the data sent and received have been acquired.

Display	Detail
"o"	Checksum is collated.
"F"	Checksum is not collated.

[Checksum off]

This instrument receives the checksum value of the data on the host side, but does not collate it with command data. Whatever the checksum data is, it is returned according to it if only the command is correct. (The checksum value of the data on the host side can be communicated as fixed to "00" or other.)

[Checksum on]

This instrument receives the checksum value of the data on the host side and collates it with command data. If any error occurs in sending/receiving data as a result of collation, it is returned as "n" and no action is taken against the command. If the result of collation agrees with the command data, it is returned accordingly.

22.2.5. Setting the terminator

If the total length of the connected cable is 15m or more or if the frequency of communication errors is high, it is recommended to install a terminator in the terminating device. Turn it on on the terminating device of the transmission line.

Display	Detail
"o"	Termination resistance
"F"	No termination resistance

22.2.6. Setting method Press the **PROG** key to change over the setting mode. Each press on the program key changes the display as follows.

Pressure display, etc.	
PROG	
\rightarrow $4 \square^{-2}$ ST1 setting: SET-1 LED blinks \longrightarrow Change the setting PROG	
$\begin{array}{c c} & & & \downarrow & \downarrow & \downarrow \\ & & \downarrow & \downarrow & \downarrow & \downarrow \\ & & & \downarrow & \downarrow$	
$\begin{array}{ c c c c } & & & \downarrow & $	
$ \begin{array}{ c c c } & & & & \downarrow \\ & & & & \downarrow \\ & & & & \downarrow \\ & & & &$	☆ ☆ ∅
$\begin{bmatrix} & & \\ & $	determine
$ \square $ $\square $	
Select "1" or "2"	
determine	
$ \begin{cases} \downarrow \\ & \\ & \\ & \\ & \\ & \\ & \\ & \\ & \\ & \\$	☆ ☆ ↓ → ↓
$ \begin{array}{ c c } & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ & & & \\ \hline & & & \\ & & & \\ \hline & & & \\ & & & \\ \hline & & & \\ & & & \\ \hline & & & \\ & & & \\ \hline & & & \\ & & & \\ \hline & & & \\ & & & \\ \hline & & & \\ & & & \\ \hline & & & \\ & & & \\ \hline & & & \\ & & & \\ \hline & & & \\ & & & \\ \hline & & & \\ & & & \\ \hline & & & \\ & & & \\ \hline & & & \\ & & & \\ \hline & & & \\ & & & \\ \hline & & & \\ \hline & & & \\ \hline & & & \\ & & & \\ \hline \\ & & & \\ \hline \\ \hline$	☆ ☆ ☆ ───
$ \begin{array}{c c} $	♪ ♪ ₽ ──
Setting sensor : Displayed setting the sensor \longrightarrow	determine
$ \begin{vmatrix} \psi \\ \text{Setting of sensor} \\ PROG \end{vmatrix} $ Change the setting	\$ \$ ₽



22.3. Standard Data Format

The table below gives the standard data sending/receiving format.

-			U			0	0				
:	AD0	AD1	CMD	D0	••••	Dn	SH	SL	CHKH	CHKL	CR
	:		Colon								
		AD0	Device ad	Device address high order (0 - 9)							
		AD1	Device ad	dress lov	w order (C) - 9)					
	CMD Various commands (note uppercase character/lowercase character)										
D0 Data											
		Dn	Data								
		SH	High order of status								
		SL	Low order	of statu	S						
		CHKH	High orde	r of chec	ksum (0 -	- 9, A - 1	F)				
		CHKL	Low order of checksum (0 - 9, A - F)								
		CR	Carriage r	eturn							

- * A command consists of uppercase characters and lowercase characters of alphanumeric characters.
- * Checksum is an exclusive logic sum (XOR) from AD0 to SL.
- * Convert all with the ASCII code.

22.3.1. Command list

Command	Description	Command	Description
D	Reads measurement value and status	1W	Writes setpoint1
SR	Reads status	2W	Writes setpoint2
SW	Writes status	3W	Writes setpoint3
Т	Reads software	ZER	Adjusts SW1 zero point
1R	Reads setpoint1	ATM	Adjusts SW1 atmospheric pressure
2R	Reads setpoint2	CLR	Resets adjustment of SW1 zero point, atmospheric pressure adjustment
3R	3R Reads setpoint3		CCM zero point adjustment
		CCR	Resets CCM zero point adjustment

22.3.2. When received normally

The following is returned when data is normally received.

When a pressure value is returned

When writing setpoint or adjusting

 : AD0
 AD1
 o
 CHKH
 CHKL
 CR

 * 'o' is a lowercase character.

22.3.3. When receiving is faulty

The following is returned when not normally received or when there is no command.

: AD0 AD1 n CHKH CHKL CR

* 'o' is a lowercase character.

22.4. Command

22.4.1.	Reading the	e measurement	value/status

Command : AD0 AD1 D CHKH CHKL CR

Format of returning from this instrument to PC

: AD0 AD1 D X . X X E ± X X SH SL CHKH CHKL CR

* The measured pressure value is entered in the "X.XXE±XX" section.

Example 1: 3.00E+03 \Rightarrow 3.00×10⁺³

Example 2: $5.00E+00 \Rightarrow 5.00 \times 10^{+0}$

Example 3: 4.00E-01 \Rightarrow 4.00×10⁻¹

- * Measurement range is exceeded when "F.FFE+FF" is returned
- * Filament has burnt out when "E.EEE+EE" is returned.
- * Refer to the relevant section for the status "SH" and "SL".

22.4.2. Writing status

Command that instructs filament ON/OFF, DEGAS ON/OFF and others.

Command : AD0 AD1 SW CHKH CHKL CR

- * Refer to the relevant section for statuses "SH" and "SL".
- * If a command is normally received, normal receipt 'o' is returned.
 If a command is correct, normal receipt 'o' will be returned even when a status that cannot be functionally possible is written.

22.4.3. Reading a status

Filament state and setpoint operational state can be confirmed.								
Command	:	AD0	AD1	SR	CHKH	CHKL	CR	

Format of return from this instrument to PC

:	AD0	AD1	S	SH	SL	CHKH	CHKL	CR
	* Refe	er to the re	elevant se	ction for	the status	"SH" and	ł "SL".	

22.4.4. Reading the software version

Command : AD0 AD1 T CHKH CHKL CR

Format of return from this instrument to PC

:	AD0	AD1	Т	Ι	S	G	3	1	1	CHKH	CHKL	CR

- * "ISG" denotes model name and "211" denotes software version Ver2.11.
 * Version is subject to shares mid-set patient.
 - * Version is subject to change without notice.
- 22.4.5. Reading setpoint1 value

	Command	:	AD0	AD1	1R	СНКН	CHKL	CR
--	---------	---	-----	-----	----	------	------	----

Format of returning from this instrument to PC

:	AD0	AD1	1	Х	•	Х	Х	Е	+	Х	Х	СНКН	CHKL	CR
	* " <u>+</u>	" denot	es "+"	or "-'	' .									

22.4.6. Reading the setpoint2 valueCommand:AD0AD12RCHKHCHKLCR

Format of returning from this instrument to PC

:	AD0	AD1	2	Х	•	Х	Х	Е	±	Х	Х	CHKH	CHKL	CR
	* " <u>+</u>	" denot	es "+"	or "-"	' .									

22.4.7. Reading the setpoint3 value

Command : AD0 AD1 3R CHKH CHKL CR

Format of returning from this instrument to PC

:	AD0	AD1	3	Х	•	Х	Х	Е	+	Х	Х	CHKH	CHKL	CR
	* "+	" denot	es "+"	or "-'										

22.4.8. Writing the setpoint1 set value

Command : AD0 AD1 IW X . X	X E ±	XX	CHKH	CHKL	CR
----------------------------	-------	----	------	------	----

- * A numeric value that can be set varies with each sensor. If a value lower than the lower limit set value of each sensor is set, it will be set at the lower limit value of setting or, if a value higher than the higher limit set value, it will be set at the higher limit value of setting.
- * Internal mantissa part comparison processing is done at 2 digits below decimal point $[\Box.\Box\Box \times 10^{-\Box\Box}]$.
- * If a command is normally received, 'o' of normal receipt will be returned.

22.4.9. Writing the setpoint2 set value

Command	:	AD0	AD1	2W	Х	•	Х	Х	Е	±	Х	Х	CHKH	CHKL	CR	l
---------	---	-----	-----	----	---	---	---	---	---	---	---	---	------	------	----	---

- * A numeric value that can be set varies with each sensor. If a value lower than the lower limit set value of each sensor is set, it will be set at the lower limit value of setting or, if a value higher than the higher limit set value, it will be set at the higher limit value of setting.
- * Internal mantissa part comparison processing is done at 2 digits below decimal point [□.□□ × 10^{-□□}].
- * If the command is normally received, 'o' of normal receipt will be returned.

22.4.10. Writing the setpoint3 set value

- Command : AD0 AD1 3W X . X X E ± X X CHKH CHKL CR
 - * A numeric value that can be set varies with each sensor. If a value lower than the lower limit set value of each sensor is set, it will be set at the lower limit value of setting or, if a value higher than the higher limit set value, it will be set at the higher limit value of setting.
 - * Internal mantissa part comparison processing is done at 2 digits below decimal point $[\Box \Box \Box \times 10^{-\Box \Box}]$.
 - * If the command is normally received, 'o' of normal receipt will be returned.
- 22.4.11. SW1 ZERO point adjustment command
 - Command : AD0 AD1 ZER CHKH CHKL CR
 - * Adjustable pressure range: Approx. ±1Pa
 - * Signal for zero point adjustment is output from the I/O connector.
 - * If a command is normally received, normal receipt 'o' will be returned though adjustment is not made. Read the measurement value and others after adjustment and check them.

22.4.12. SW1 atmospheric pressure adjustment command

- Command : AD0 AD1 ATM CHKH CHKL CR
 - * The adjustable pressure range is 1×10^{-4} to 2×10^{-5} Pa
 - * Signal for atmospheric pressure adjustment is output from the I/O connector.
 - * If a command is normally received, normal receipt 'o' will be returned though adjustment is not made. Read the measurement value and others after adjustment and check them.

22.4.13. SW1 zero point, atmospheric pressure adjustment correction reset command

Command : AD0 AD1 CLR CHKH CHKL CR

- * Reset signal is output from the I/O connector.
- * If the command is normally received, normal receipt 'o' will be returned.

22.4.14. CCM zero point adjustment command

- Command : AD0 AD1 CZR CHKH CHKL CR
 - * The adjustable pressure range is about ± 20 mV.
 - * Arithmetically processed in this instrument.
 - * If a command is normally received, normal receipt 'o' will be returned though adjustment is not made. Read the measurement value and others after adjustment and check them.

22.4.15. Zero point, atmospheric pressure adjustment correction reset command

- Command : AD0 AD1 CCR CHKH CHKL CR
 - * Arithmetic processing in this instrument is reset.
 - * If the command is received normally, normal receipt 'o' will be returned.

22.5. Checksum

Checksum is for checking if data sent has been received correctly. Without checksum, this instrument cannot send/receive data.

Checksum calculates from address to Xor of the character preceding the check sum.

Checksum can be calculated more conveniently by using "calculator" in the windows. Select the alpha calculator from the types of calculators and calculate by hexadecimal notation.

22.5.1. Example: when reading the measurement value of address 11 and status

「**31**」

The following tables give the commands and ASCII coder when reading the measurement value and status of address 11.

Command(ASII)	:	1	1	D	CHKH	CHKL	CR
		\downarrow	\downarrow	\downarrow			
Hex		31	31	44	CHKH	CHKL	CR
					1		

Here, calculate from the address to the character before the checksum with Xor, equal 44. Don't calculate [:(3A)]

[31]

Xor

[44∣

= 44

Xor

Accordir	ngly	, the	accu	rate	comr	nand	is as	folle	ows.								
Command(ASI	I)	:		1		1		D)	4		4		CR		
Given th	a <u>t t</u> ł	ne me	easur	eme	nt va	lue at	this:	time	is tl	ne fol	lowi	ng st	ring,				
Command (ASII)	:	1	1	D	1	•	0	0	Е	+	0	5	F	6	4	0	CR
		↓	\downarrow		\downarrow	↓	\downarrow	↓									
Hex		31	31	44	31	2E	30	30	45	2B	30	35	46	36	CHKH	CHKL	CR
								\checkmark						\bigcirc			
	۲ 31	.]	Xor	ſ	31」	X	or	İ44	J	Xor	٢	31」	Xo	or	2E	Xor	
	۲ 3 0)]	Xor	Γ	30	X	or	۲45	J	Xor	Γ	2 B _	X	or	「 30 」	Xor	
	٢35	5]	Xor	ſ	46	X	or	۲ 36	J								
	=	「 40 」															

Thus, calculating from the address to the character preceding the checksum, we obtain "40" and can judge that the data has been received correctly.

Don't calculate [:(3A)]

22.6. Status Setting List

22.6.1. When writing

Only BMR2, SC1, SH2, ST2, SH200, ST200

SH	(high	order	Status)
----	-------	-------	---------

		0 [30H]	8 [38H]	C [43H]	4 [34H]	D [44H]	5 [35H]
B7	FIL-2/1	0	1	1	0	1	0
B6	FIL-ON/OFF	0	0	1	1	1	1
B5	N·C	0	0	0	0	0	0
B4	DEGAS-ON/OFF	0	0	0	0	1	1

FIL-2/1	1: FIL1	0: FIL2
$\lceil Sn1 \rfloor \lceil SC1 \rfloor : FIL(HV) \text{ ON/OFF}$	1: ON	0: OFF
「Sh2」「SPU」「SAU」:FIL OFF/ON	1: OFF	0: ON
DEGAS-ON/OFF	1: ON	0: OFF

SL (low order 4 Status)

		0 [30H]	F [46H]
B3	N·C	0(X)	1(X)
B2	N·C	0(X)	1(X)
B1	N·C	0(X)	1(X)
B0	N·C	0(X)	1(X)

* The N.C portion can also be actuated with [1] or [0].

* SC1 does not have FIL 1/2 or DEGAS, so this part works with either [1] or [0].

The data configuration of the reading status and that of the writing status are similar, but they differs from the those of reading/writing values to the same register.

Therefore, the low order of the reading status will not be [F] even if [F] is written in the low order when writing.

22.6.2. When reading SH (high order Status) * CCM: This SH is all "0" = plus

		0 [30H]	4 [34H]	6 [36H]	5 [35H]	7 [37H]
B7	FIL-2/1	0	0	0	0	0
B6	FIL-ON/OFF	0	1	1	1	1
B5	Em.Valid	0	0	1	0	1
B4	DEGAS-ON/OFF	0	0	0	1	1

		8 [38H]	C [43H]	E [45H]	D [44H]	F [46H]
B7	FIL-2/1	1	1	1	1	1
B6	FIL-ON/OFF	0	1	1	1	1
B5	Em.Valid	0	0	1	0	1
B4	DEGAS-ON/OFF	0	0	0	1	1

FIL-2/1	1: FIL-1	0: FIL-2
$\lceil Sn1 \rfloor \lceil SC1 \rfloor : FIL(HV) \text{ ON/OFF}$	1: ON	0: OFF
「Sh2」「SPU」「SAU」:FIL OFF/ON	1: OFF	0: ON
Em.Valid	1: OK	0: NG
DEGAS-ON/OFF	1: ON	0: OFF

SL (low order Status)

		0 [30H]	1 [31H]	2 [32H]	3 [33H]	4 [34H]
B3	PROTECT	0	0	0	0	0
B2	SETPOINT3	0	0	0	0	1
B1	SETPOINT2	0	0	1	1	0
B0	SETPOINT1	0	1	0	1	0

		5 [35H]	6 [36H]	7 [37H]	8 [38H]
B3	PROTECT	0	0	0	1
B2	SETPOINT3	1	1	1	0
B1	SETPOINT2	0	1	1	0
B0	SETPOINT1	1	0	1	0

PROTECT	1: ON	0: OFF
SETPOINT3	1: ON	0: OFF
SETPOINT2	1: ON	0: OFF
SETPOINT1	1: ON	0: OFF

22.7. ASCII Code Table

ASII	Hex	ASII	Hex	ASII	Hex	ASII	Hex
(nul)	00	(sp)	20	@	40	•	60
(soh)	01	!	21	А	41	a	61
(stx)	02	"	22	В	42	b	62
(etx)	03	#	23	С	43	с	63
(eot)	04	\$	24	D	44	d	64
(enq)	05	%	25	Е	45	e	65
(ack)	06	&	26	F	46	f	66
(bel)	07	4	27	G	47	g	67
(bs)	08	(28	Н	48	h	68
(tab)	09)	29	Ι	49	i	69
(lf)	0A	*	2A	J	4A	j	6A
(vt)	0B	+	2B	K	4B	k	6B
(ff)	0C	,	2C	L	4C	1	6C
(cr)	0D	-	2D	М	4D	m	6D
(so)	0E		2E	Ν	4E	n	6E
(si)	0F	/	2F	0	4F	0	6F
(dle)	10	0	30	Р	50	р	70
(dc1)	11	1	31	Q	51	q	71
(dc2)	12	2	32	R	52	r	72
(dc3)	13	3	33	S	53	S	73
(dc4)	14	4	34	Т	54	t	74
(nak)	15	5	35	U	55	u	75
(syn)	16	6	36	V	56	v	76
(etb)	17	7	37	W	57	w	77
(can)	18	8	38	Х	58	Х	78
(em)	19	9	39	Y	59	у	79
(sub)	1A	:	3A	Z	5A	Z	7A
(esc)	1B	;	3B	[5B	{	7B
(fs)	1C	<	3C	¥	5C		7C
(gs)	1D	=	3D]	5D	}	7D
(rs)	1E	>	3E	^	5E	~	7E
(us)	1F	?	3F	_	5F	(del)	7F

23. TROUBLESHOOTING

Possible causes of malfunction of this unit include erroneous electric wiring. If any trouble is suspected, check the following.

- (1) Wiring between the display unit and sensor unit
- (2) Wiring between the display unit and remote host
- (3) Short/open signal

Refer to the troubleshooting chart below after checking these. The arrow mark $[\rightarrow]$ in the corrective action column represents the reference page.

Turn off the power before making these checks.

① No display appears when power is turned on.

Possible cause	Corrective action
Erroneous wiring or disconnection of the	Correct the wiring and check continuity using a
power supply cable	circuit tester.
Line voltage is below the specified range.	Check the line voltage using a voltmeter. Line
	voltage is to be within 24V±1V.
CPU has run out of control because of	Turn on the power again to start up CPU again.
external noise.	
	Corrective measures against noise should be taken
	otherwise.
Internal fuse has blown out.	Check and/or repair at ULVAC are necessary.
Failure of display unit indicating circuit.	Check and/or repair at ULVAC are necessary.
Failure in the display unit circuit.	Check and/or repair at ULVAC are necessary.

2 Pressure has changed, but the indication remains constant.

Possible cause	Corrective action
Pressure is below the measurement range.	Normal
Erroneous wiring between sensor unit and	Correct the wiring and check continuity using a
display unit (pressure signal is not input to	circuit tester or other.
the display unit) or wiring is broken.	
Cable connecting the sensor unit and the	Reconnect the cable and fix it securely.
sensor head is disconnected (when the box	
unit is used).	
Line voltage is too low.	Check the line voltage using a circuit tester.
	Line voltage: 24V±1V

③ [FU LL] is not displayed under atmospheric pressure

Possible cause	Corrective action		
The sensor head or cable length differs from	Change it with a specified one or recalibrate it wit		
the specified one.	the current one.		
	\rightarrow Refer to the sensor unit manual		
Gas under measurement is not air.	Normal		
	\rightarrow Refer to the sensor unit manual		
Gas under measurement is air, but it contains	Normal		
much water and/or oil.	\rightarrow Refer to the sensor unit manual		

④ Pressure display does not indicate a constant value.

Possible cause	Corrective action
Pressure is changing.	Normal
The type of sensor unit differs from the	Change it with the specified one. Or readjust and
specified one.	recalibrate the sensor being used.
The sensor head is contaminated or the	Replace the sensor.
sensor head filament has worn out.	\rightarrow Refer to the sensor unit manual.
There is a leak in the sensor head or in the	Leak in the sensor.
vicinity of the portion where the sensor head	\rightarrow Replace the sensor.
is installed.	Other leak
	\rightarrow Stop the leak.
Poor contact of the sensor head cable or	Check cable connection.
increased resistance of the wire rod due to	
corrosion.	
The cable is subject to electromagnetic	Change the cable laying position. Or turn off a
induction (by external noise).	component that can be a source of noise.
	Recheck the method of laying cables.
	Examine measures against noise otherwise.

(5) The indicated pressure value differs largely from expected value.

Possible cause	Corrective action	
The sensor head is contaminated and	Change the sensor with another one and check	
sensitivity has lowered noticeably.	symptom. If ok with another sensor, there is a	
	problem in the sensor.	
	\rightarrow Refer to the sensor unit manual.	
Failure of the internal circuit in the display	Check and/or repair at ULVAC is necessary.	
unit.		
(The sensor unit itself operates normally.)		
The actual pressure differs from the expected	Check pressure using another vacuum gauge.	
pressure.		

24. WARRANTY

This product was shipped after rigid company inspection. However, in case any failure occurs under ULVAC's responsibility, such as defect in manufacturing and damage during transportation, Buyer shall inform ULVAC, Inc. or the local ULVAC representatives. ULVAC will repair or exchange it at free of charge.

Warrantable Items

1) This unit

Duration of guarantee

Within 1 year from the date of delivery.

Warranty scope

- 1) Domestic business in Japan: Product, which has damage, caused by a failure on delivery.
- 2) Direct export transaction: Product, which has damage, caused by a failure on delivery. The warrantee scope shall confirm to the new INCOTERMS.
- 3) Products not satisfying meet the standard specifications although the product is used under the normal service conditions such as temperature range and power etc.

Response procedure

- 1) Domestic business in Japan: ULVAC send a replacement or customer return the defective items to ULVAC, Inc. or to the local ULVAC representatives for repair. If field service is required, customer shall ask ULVAC, Inc. or the local ULVAC representatives.
- 2) Direct export transaction: ULVAC send a replacement or customer return the defective items to ULVAC, Inc. or to the local ULVAC representatives for repair. Return charge shall be paid by customer.

Disclaimer

- 1) Failure occurred after expiration of warranty period
- 2) Failure caused by force majeure, such as fire, storm and flood damage, earthquake, lightning strike, war etc.
- 3) Failure occurred due to carelessness handling or faulty usage.
- 4) Products remodeled, disassembled or repaired without ULVAC's acceptance.
- 5) Failure occurred under abnormal environment, such as intense electromagnetic field, radiation, high-temperature, high-humidity, flammable gases, corrosive gases, dust etc.
- 6) Failure occurred by noise.
- 7) Product deficiency or secondary damnification occurred to Buyer, from law suit to ULVAC by third party for patent infringement.
- 8) Sensor head being used (expiration of life, measurement error, etc.)
- 9) Sensor head cable in use (cable burnout due to improper installation, poor contact, etc.)

Others

- 1) If there is a separate contract or memorandum regarding specifications besides this instruction manual, the contents of the contract or memorandum will be followed.
- 2) Customer shall inform ULVAC when this product is exported out of Japan. In the meantime, customer shall take necessary procedures according to Foreign Exchange and Foreign Trade Law.
- 3) As for the question and consultation, customer shall check the model and serial number and ask the local representative or ULVAC, Inc.
- 4) The content of this document is subject to change without notice in future.

25. China RoHS Declaration



This mark is applied to the electronic information product sold in the People's Republic of China. The figure at the center of the mark is the validity date of environmental protection. This product does not influence the environment, the human body and the property during the period reckoning the manufacturing date as long as the cautions for safe use regarding the products are observed.

*The environmental protection validity date is not the product warranty period.

Table1. Making format for names and contents of hazardous substances or elements

	Hazardous substances or elements					
Name of parts	Pb	Hg	Cd	Cr ⁶⁺	PBB	PBDE
Printed Circuit Board	×	0	0	0	0	0
Chassis	×	0	0	0	0	0
Connector	×	0	0	0	0	0
AC-DC Converter	×	0	0	0	0	0
Label	0	0	0	0	0	0

 o: indicating that content of the hazardous substance or element in all homogeneous materials of the part does not exceed the requirements for concentration limits specified by SJ/T11363-2006.

x: indicating that content of the hazardous substance or element in, at least one kind of, homogeneous materials of the part exceeds the requirements for concentration limits specified by SJ/T11363-2006. Producer may further explain the technical excuse to the items marked with "X" perspecific conditions here. 26. EC DECLARATION OF CONFORMITY

ULVAC	
CE Decl	aration of Conformity CE
We, Company:ULVAC ,Inc.	
of Address:2500 HAGISC	DNO, CHIGASAKI, KANAGAWA, 253-8543 Japan.
This declaration is issued under In accordance with the following	r the sole responsibility of the manufacturer. g Directive:
EN IEC63000:2018	RoHS Directive (2011/65/EU)
declare under our sole responsi	ibility that the product,
Type of Product	: 1CH Display Unit
Model Name	: ISG1
to which this declaration related EN61326-2-3:2013 EMC Directive (2014/30/EU) EN IEC61000-4-2:2008 Electrostatic Test EN IEC61000-4-3:2006+A Radiated Electromagnetic Fiel EN IEC61000-4-4:2004+A Transient Burst Test EN IEC61000-4-5:2005 Surge Test EN IEC61000-4-6:2008 Conduction Test EN IEC61000-4-8:2009 Commercial Magnetic Field Te CISPR11:2009+A1:2010 Radiation Field Intensity Meas following the provisions of The person stated below will keep the operating and maintenance instru- technical drawings description of measures designed other technical documentation, e.g	A1:2007+A2:2010 Id Test A1:2010 est Group 1 Class A surement e following technical documentation: ctions I to ensure conformity g. quality assurance measures for design and production
Person authorized to compile to (Name and address) Julian Weck ULVAC GmbH, K	he technical file: Jausnerring 4, 85551 Kirchheim b. München, Germany
19 Oct, 2022 To Kanagawa , Japan Se (date & place)	oyoaki Nakajima enior Manager of Components Division T. Ashajima (name, function, signature)
	Form:A00315287-01-01

27. UKCA DECLARATION OF CONFORMITY

ULVAC	
UK CA <u>D</u> e	eclaration of Conformity CA
We, Company:ULVAC ,	Inc.
of Address:2500 HAG	GISONO, CHIGASAKI, KANAGAWA, 253-8543 Japan.
This declaration is issued un In accordance with the follow	nder the sole responsibility of the manufacturer. wing Directive:
BS EN IEC63000:2018	RoHS Directive (2011/65/EU)
declare under our sole resp	onsibility that the product,
Type of Product	: 1CH Display Unit
Model Name	: ISG1
to which this declaration rela BS EN61326-2-3:2013 EMC Directive (2014/30/E BS EN IEC61000-4-2:2 Electrostatic Test BS EN IEC61000-4-3:2 Radiated Electromagnetic BS EN IEC61000-4-4:2 Transient Burst Test BS EN IEC61000-4-5:2 Surge Test BS EN IEC61000-4-6:2 Conduction Test BS EN IEC61000-4-8:2 Commercial Magnetic Fie BS CISPR11:2009+A1 Radiation Field Intensity M following the provisions of The person stated below will keep operating and maintenance in technical drawings description of measures desig other technical documentation	ated is in conformity with the following standards: 3 5U) 2008 2006+A1:2007+A2:2010 5 Field Test 2004+A1:2010 2005 2008 2009 Hd Test 1:2010 Group 1 Class A Measurement p the following technical documentation: Instructions gned to ensure conformity n, e.g. quality assurance measures for design and production
Person authorized to comp (Name and address) Julian Weck ULVAC Gmb	ile the technical file: oH, Klausnerring 4, 85551 Kirchheim b. München, Germany
19 Oct, 2022 Kanagawa , Japan (date & place)	Toyoaki Nakajima Senior Manager of Components Division (name, function, signature)
	Form:A00315287-02-00

28. Certificate of Decontamination



Form: A00315268-02-00

ULVAC Components / Certificate of Decontamination

This is a certificate of decontamination for repair and inspection request of ULVAC Components. All material must be certified as decontaminated and this certificate must be submitted to your closest local ULVAC service center or sales office prior to shipment.

Please consult with your closest local ULVAC service center or sales office if our components are used with toxic gases or contaminated with reactive products or substances produced by reaction.

Product model: Model: Serial No.: Application: Remarks:

Contaminant (Check an applicable box.)

 \Box I guarantee that above returned item(s) is not contaminated with harmful substances. \Box Above returned item(s) is contaminated with the following harmful substances.

Above returned item(s) is contaminated with the following harmful substances.

	Name of contaminant (molecular formula)	Characteristics
1		
2		
3		
4		
5		

To: ULVAC Attn:

	Date.	/ /	(1111/MM/DD)
Your company			
Division			
Contact			
Phone			
Fax			
E-mail			

Please pack returned item(s) carefully before shipment. Any accident occurred during transportation to us and during disassembly caused by contaminant is under your responsibility. It is also to be understood that ULVAC may decline to repair returned item(s) depending on the type of contaminant and degree of contamination, and return it to you.

To be filled in by ULVAC	Received by	
Request for SDS: Yes/No	neccivea sy	
ULVAC job No.		