



Dear Valued Customer.

01 February 2021

ULVAC Components News

Thank you for the continuous business with us.

This is to inform you that we will replace the standard Oil / ULVOIL for Oil Rotary Vacuum Pump and Mechanical Booster Pump with a higher performance type vacuum pump oil.

We are planning to discontinue production of the R-7 and R-4, which have been patronized for many years, although they will still be available for sale for a while.

We highly value our business connection and are looking forward to serving you.

【 Object products and changes 】

Oil Rotary Vacuum Pump	Current	New type to be used
VD Series	ULVOIL R-7	ULVOIL R-72
VS Series		
PVD Series		
PKS Series		
Mechanical Booster Pump	Current	New type to be used
PMB Series	ULVOIL R-4	ULVOIL R-42
PRC Series		

【 Reason for the changes 】

ULVOIL R-72 and R-42 are vacuum pump oil with highly anti-emulsifying properties that prevent the emulsification phenomenon in which water and oil mix in a vacuum pump, with the aim of reducing the frequency of oil changes.

【 Revision date 】

All purchases received from 1. April. 2021.

【 Attached files 】

PN-WP10-008-00E/R-72 and R-42 Feature Introduction < PN-WP10-008-00E >

【 MEMO 】

- There is no price revision of the vacuum pump due to the change of vacuum pump oil.
- There is no problem with pump performance even if R-7 (R-4) and R-72 (R-42) are mixed.

Sincerely

Munenori Tada
Senior Manager
Components Business Planning Dept.

End of Document